| Form 3160-5 November 1983) Formerly 9-331) | UNITED STATES DEPARTMENT F THE INTERIOR | NM OIL CONS COMMIS SUBMIT IN TRIPI TE* (Draw actable lions | Expires August 31, 1985 |
|---|---|---|--|
| | BUREAU OF LAND MANAGEMENT | Artesia, NM 88210 | 5. LEASE DESIGNATION AND BERIAL NO. NMNM 27276 |
| (Do not use this | DRY NOTICES AND REPORTS ON form for proposals to drill or to deepen or plug back Use "APPLICATION FOR PERMIT—" for such propo | WELLS to a different reservoir. | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| OIL X GAS WELL | OTHER | | 7. UNIT AGREEMENT NAME |
| 2. NAME OF OPERATOR C.E. LAR | TIE: | RECEIVED | 8. FARM OR LEASE NAME |
| 3. ADDRESS OF OPERATOR | | | MC CLAY |
| PO BOX 4 | | SEP 27. ' 94 | 9. WBLL NO. 9 |
| See also space 17 bel At surface | Report location clearly and in accordance with any States ow.) | te requirements. | 10. FIELD AND POOL, OR WILDCAT |
| | L AND 1650' FEL T18S, R30E | O. C. D. ARTESIA, OFFICE | N. BENSON QUEEN GRAYBURG 11. SEC., T., B., M., OR BLK. AND SURVEY OR ARMA |
| 14. PERMIT NO. | 15. ELEVATIONS (Show whether DF, RT | , GR. etc.) | SEC. 33, T18S, R30E |
| API# 30-015-216 | , i | | 12. COUNTY OR PARISH 13. STATE EDDY NM |
| 16. | Check Appropriate Box To Indicate Nat | ure of Notice Report or O | Other Data |
| | NOTICE OF INTENTION TO: | | ENT REPORT OF: |
| TEST WATER SHUT-O | PULL OR ALTER CASING | WATER SHUT-OFF | REPAIRING WELL X |
| FRACTURE TREAT SHOOT OR ACIDIZE | MULTIPLE COMPLETE | FRACTURE TREATMENT | ALTERING CASING |
| REPAIR WELL | ABANDON* | SHOOTING OR ACIDIZING | ABANDONMENT® |
| (Other) | | (Other) | of multiple completion on Well |
| DESCRIBE PROPUSED O proposed work. If nent to this work.) | R COMPLETED OPERATIONS (Clearly state all pertinent d well is directionally drilled, give subsurface location | etails, and give pertinent dates, s and measured and true vertica | etion Report and Log form.) including estimated date of starting any idepths for all markers and zones perti- |
| POOR. PULLED R VALVE. RAN PU | ODS AND PUMP OUT. DROPPED STANDI MP AND RODS IN. HUNG WELL ON. L | NG VALVE. LOAD TUBI | HUNG WELL ON. PUMP ACTION NG WITH 500#. FISHED STANDING TO GET PRESSURE. PULLED RODS CLOSED TOP VALVE. SHUT DOWN |
| RIGGED UP FOR R | WELL. RIGGED UP FOR TUBING. PUD STANDING VALVE. RAN TUBING BACODS. RAN PUMP AND RODS IN. RESPONCE | K IN. REPLACED BAD | JOINT. LANDED TUBING. |
| | TROKED PUMP. WAIT ON HOT OILER. PUMP ACTION. RIGGED DOWN AND CLE | | STROKED AT 300#. HUNG |
| | | | |
| | | y fara | |
| | | 2 3 1994 | . 3 |
| | | | \$ - 1 |
| | | | |
| 2- | t the foregoing is true and correct | SE DECORDS | 9 94 04 |
| SIGNED SIGNED | 7 | SE RECORDS | 8-24-94 |
| (This space for Fed | Fal or State office use) | | |
| APPROVED BY CONDITIONS OF A | PPROVAL, IF ANT: | | DATE |
| | | | |