

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-015-21622
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE
State Oil & Gas Lease No. F-2211
Lease Name or Unit Agreement Name Yates State
Well No. 6
Pool name or Wildcat Benson Queen Grayburg-North

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL OTHER	
Name of Operator Yates Energy Corporation	
Address of Operator PO Box 2323 Roswell, New Mexico	
Well Location Unit Letter H : 1980 Feet From The North Line and 990 Feet From The East Line Section 32 Township 18S Range 30E NMPM Eddy County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3400' GL	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON  
TEMPORARILY ABANDON CHANGE PLANS  
PULL OR ALTER CASING  
OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING  
COMMENCE DRILLING OPNS. ☒ PLUG AND ANBANDONMENT ☒  
CASING TEST AND CEMENT JOB  
OTHER:

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify OCD of intent to plug
2. 5/11/98 Set 4 1/2" CIBP @ 2905 W/35' cement
3. 5/11/98 RIH circulate well w/9.8# mud
4. 5/12/98 Set 25 sx cement from 2703' to 2341'
5. 5/12/98 Set 25 sx cement from 1400' WOC/tag @ 1012'
6. 5/13/98 cut and pulled 4 1/2" casing @ 397'
7. 5/13/98 Spot 25 sx cement from 497' WOC/tag @ 426'
8. 5/13/98 Spot 30 sx cement from 426' WOC/tag @ 256'
9. 5/14/98 Spot 10 sx cement from 30' to surface
10. 5/18/98 Cut off well head, set dry hole marker, clean location

Post ID-1  
7-14-98  
PWA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *N. Wayne Brooks*

TITLE Operations Supervisor  
Dawson Production Services

DATE 05-18-98

TYPE OR PRINT NAME N. Wayne Brooks

TELEPHONE NO. (915) 683-5321

(This space for State Use)

APPROVED BY

*[Signature]*

TITLE

*[Signature]*

DATE

11/30/98

CONDITIONS OF APPROVAL, IF ANY:

