

50-015-21737

4-21-76

Gamma Ray Neutron
5330 - 6339

Dual Laterlog Micro SFL
560 - 6338

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1290
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

CISF
BP

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.

30-015-21737

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

BP America Production Company

8. Well No.

232

3. Address of Operator

P.O. Box 1089 Eunice, NM 88231

9. Pool name or Wildcat

Empire Abo

4. Well Location

Unit Letter G : 2253 Feet From The N Line and 1576 Feet From The E Line

Section 6 Township 18S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3674.6' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Workover ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6345' PBD: 6336' PERFS: 5984-6160' (new), 6184-6197' (old)

03.12.02: MIRUPU. NDWH. NUBOP. Unset pkr & POH w/tbg, SN & pkr. RIH w/bit, scraper, and 2-3/8" tbg.

03.13.02: Tag @ 6223'. POH w/tbg & tools. RIH w/RBP, SN & 198 jts tbg. Tested in hole. Set RBP @ 6178'. POH.

03.14.02: Finish POH. RUWL. SION due to wind.

03.15.02: RUWL & perf 5984-6160'. RDWL. RIH w/pkr, SN, 2-3/8" tbg to 6160'. RIH w/swab to SN. No fluid.

03.18.02: RU acid truck & spot 200 gals 15% HCL NEFE acid f/6160-5960'. PU & POH w/9 jts. Set pkr @ 5881'. Acidize perfs w/3250 gals 15% HCL NEFE. Displace w/28 bbls 2% KCL fresh wtr. RD acid truck. Rls pkr. RIH w/10 jts & latch on to RBP. RIH w/ 198

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Sr. Administrative Assistant DATE 04.23.02

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

APR 26 2002

Empire Abo Unit J-232
Workover Operations
03.11.02

03.18.02 cont: jts 2-3/8" tbg. Set @ 6189'. SN set @ 6190'. NDBOP. NUWH.

03.19-22.02: Swab well. Well SI.