

Form 3160-5  
(June 1990)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Oil Cons.  
N.M. DIV-Dist. 2  
1301 W. Grand Avenue  
Artesia, NM 88210

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
ARCO Permian

3. Address and Telephone No.

P.O. Box 1089, Eunice, NM 88231 505-394-1649

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter H, 2490' FNL & 1299' FEL  
Section 1, T18S, R27E

5. Lease Designation and Serial No.

6. Indian, Allottee or Tribe Name

EMPIRE ABO UNIT

7. If Unit or CA, Agreement Designation

NM-70945

8. Well Name and No.

Empire Abo Unit "J" 202

9. API Well No.

30-015-21783

10. Field and Pool, or exploratory Area

Empire Abo

11. County or Parish, State

Eddy NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other Workover  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRUPU. NDWH. NUBOP. RU Wireline unit. RIH w/SV & set in SN @ 5833'. POH. GIH & chemically cut 2-3/8" tbg in second jt. above pkr. POH w/wireline & chemical cutter. RDWL unit. POH w/tbg. GIH w/overshot, API SN, & workstring to top of fish. Swab well down to SN. If well begins to flow kill well w/1 bbl. 2% KCL wtr. GIH catch fish. Release pkr @ 5838'. POH. RIH w/4-3/4" bit & scraper to PBTD @ 6270'. POH. GIH & perf w/2 JSPF 5614 to 5618, 5625 to 5628, 5650, 5663 to 5670, 5685 to 5691, 5710 to 5714, 5719 to 5724, 5730 to 5740, and 5793. POH. GIH w/ PPI tools & breakdown perfs from 5793 to 5614 w/50 gals/ft. 15% HCL NEFE. POH. GIH w/ bull plugged MA, perf sub, API SN & 2-3/8" tbg. Land SN @ +/- 6206'. NDBOP. NUWH. Swab for test. RDPU. RTP.

14. I hereby certify that the foregoing is true and correct

Signed

Title Sr. Administrative Assistant

Date 08/23/01

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.

\* See Instruction on Reverse Side

RECEIVED  
2001 AUG 27 AM 9:04  
BUREAU OF LAND MGMT.  
ROSWEIL OFFICE