

NMOCC COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THE MANNER INDICATED
(Other instructions on reverse side)

copy to SF
Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

New Mexico 0924

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Alscott Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat Cisco

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 31, T-18-S, R-29-E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Hondo Drilling Company

3. ADDRESS OF OPERATOR

Drawer 2516 Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

1650' from North Line and 1980' from East Line,
Section 31, T-18-S, R-29-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3421 GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9/12/77 Set "blanking plug" in top of 5 1/2" Guiberson Packer at 11,022.61' and pulled 2 3/8" tubing out of hole.

9/13/77 Perforated 30 hole thru casing with 4" Jumbo Jet Kone shots - Zone from 9518' - 9548' Run tubing in hole and set Guiberson Packer at 9472.34'.

9/14/77 Swabbing and testing. Well flowing distillate and Gas.

9/15/77 Rigged up Halliburton, treated well with 3000 gal. 15% Acid, Swabbing and Testing well flowing distillate and gas retreat 2,000 MCF per day.

9/16/77 Testing well - 6hr. test. 2,200 MCF per day 30 bbl. condensate 3/8" choke 2200lb tubing pressure well shot in for 4 point test.

RECEIVED
OCT 31 1977
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

President

DATE

10/28/77

(This space for Federal or State office use)

APPROVED BY

[Signature]

TITLE

ACTING DISTRICT ENGINEER

DATE

NOV 11 1977

CONDITIONS OF APPROVAL, IF ANY: