

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.O.S.	
LAND OFFICE	
OPERATOR	

O. C. D.
ARTESIA OFFICE

1a. Indicate Type of Lease State <input checked="" type="checkbox"/> For <input type="checkbox"/>
5. State Oil & Gas Lease No. State 647

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- Dry
Name of Operator Yates Petroleum Corporation ✓		
Address of Operator 207 South 4th St., Artesia, NM 88210		
Location of Well UNIT LETTER K, 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 18S RANGE 28E NMPM.		

7. Unit Agreement Name
8. Form or Lease Name HY-State GH
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat Wolfcamp
12. County Eddy

15. Elevation (Show whether DF, RT, GR, etc.)
3548' GR = 3565' KB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
DRILL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well is presently completed in Wolfcamp perforations 8135-8226 and is non-commercial. Top of cement behind 5-1/2" production casing is 7225', and 8-5/8" casing is set at 2400' with cement circulated. Top of Wolfcamp is 7944', Bone Springs is 3350', San Andres at 2176'. Propose to set CIBP at about 8100' w/35' of cement, cut and pull approximately 7200' of 5-1/2" casing, set 35 sack plug across 5-1/2" stub*, 35 sack plug at 5500-5400', 35 sack plug at 3400-3300', 35 sack plug across 8-5/8" shoe* and 10 sacks at surface with dry hole marker.

* Plugs to be Tagged

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

WED <u>Edie L. Hurd</u>	TITLE <u>Engineer</u>	DATE <u>8-18-81</u>
APPROVED BY <u>W. A. Gressitt</u>	TITLE <u>SUPERVISOR, DISTRICT II</u>	DATE <u>AUG 20 1981</u>
CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time.		