


1715 480



1. TO REELAGE GUN: Run 2" or 3" positive shoring tool, or 2" Garrett - down the hole in the Sub. Drill back up to lateral in **187'** release shoring bar into release gun and then drilling tool. After gun has been released to 2" it be forced with center shoring a foot at 187'.

Total length of 80 base pin bolt in hole is 7 INCHES.
The top 4" is the flange/fingers, next 3" is 3"
dia. x 1/8" dia. with 2 3/8" EU 8-RD. pin screwed into
a 2 3/8" EU 8-RD. coupling. Total length above 2 3/8"
EU 8-RD coupling is 7".

GRASS PESTICIDES: 1041

TOP OF PAGE

2015 JAN 2009 GENS:

DOWN OVERSHOT THAT WILL EXCEED 3.063' F.O.D. FROM THE OVERSHOT MUST BE DECREASED TO PASS OVER AT LEAST 7 INCHES OF FISH BEFORE GRAPPLE REACHES TO 3.063' F.O.D. SURFACE

3.083 0.000 0.000 0.000

* SEE DIAGRAM BELOW FOR MEASUREMENTS.

* SEE DIAGRAM BELOW FOR MEASUREMENTS.

