			·
h . OF COPIES RECEIVED 3			Form C-103
DISTRIBUTION		RECEIVED	Supersedes Old
SANTA FE /	NEW MEXICO OI	L CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE /	· <u> </u>	### 0 A 4027	
U.S.G.S.		JUN 2 0 1977	5a. Indicate Type of Lease
LAND OFFICE	_]		State Fee X
OPERATOR 1	J	O. C. C.	5. State Oil & Gas Lease No.
SUND	RY NOTICES AND REPOR	RTS ON WELLS	
(DO NOT USE THIS FORM FOR PEUSE "APPLICA"	ROPOSALS TO DRILL OR TO DEEPEN (TION FOR PERMIT - " (FORM C-101	OR PLUG BACK TO A DIFFERENT RESERVOIR. } FOR SUCH PROPOSALS.)	
OIL GAS WELL X	OTHER-		7. Unit Agreement Name
2. Name of Operator MORRIS R.	A NUTLIE T I		8. Farm or Lease Name Penasco
3. Address of Operator	, ANIWEIL		9. Well No.
P. O. Box	2010 Hobbs.	New Mexico 88240	1
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER0	660 FEET FROM THE S	South LINE AND 1980 FEET FR	Undesignated Morro
F +	20	10.0	THIIIIIIII
THE LAST LINE, SECT	ION ZO TOWNSHIP	18-S RANGE 25-E NMI	··· (
	15. Elevation (Show	whether DF, RT, GR, etc.)	12. County
	3573	GR	Eddy
Check	Appropriate Box To Indi	cate Nature of Notice, Report or (Other Data
	NTENTION TO:	_	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABAND	OON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	· (FET)
		OTHER Completion	[X]
OTHER			
8662' (26 SITP 2700 sealers. SIP 2000	holes), Flwd. psi. Treated w Inj. rate 7-1/2 psi. Flwd. back e - 875 psi. FTP	casing to 2000 psi30 ed 8634'-8643', 8646'-8 4.0 MMCFPD - 3/4" choke /5000 gals acid using r b/m @ 5500 psi. ISIP load. Cleaned up. F1 SITP 2710 psi. Prep	3649', and 8651'- e - 260 psi FTP. nitrogen and ball 3000 psi. 2 min.
8. I hereby certify that the information		-	
IGNED K MWelle	ovo titi	E Agent	
210 \$	Para T	SUPERVISOR, DISTRICT, H	JUN 2 3 1977

SUPERVISOR, DISTRICT, H