

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

STRICT I
Box 1980, Hobbs, NM 88240

STRICT II
Box 1980, Hobbs, NM 88240

STRICT III
Box 1980, Hobbs, NM 88240

WELL API NO. 30-015-22140
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-6973
7. Lease Name or Unit Agreement Name West 4-Dinkus "HZ" State
8. Well No. 1
9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P & A <input type="checkbox"/>	Name of Operator YATES PETROLEUM CORPORATION
Address of Operator 105 South Fourth Street - Artesia, NM 88210	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3750' KB

Well Location
Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line

Section 22 Township 18S Range 24E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3750' KB

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
DILL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Continued from previous page:

outside casing. Spotted 47 sacks Class "C" 2% CaCl2 from 1050' (50' inside stub). Pull up tubing & WOC. Tagged at 1000'. Respot additional 45 sacks Class "C" 2% CaCl2 at 1000'. Pulled up and WOC. Tagged at 900'. Spot 57 barrels plugging mud from 900' to surface. Spot 27 sacks Class "C" 2% CaCl2 from 368-268' in 8-5/8" casing. Set a 10 sack plug at surface. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed February 23, 1994.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE Feb. 24, 1994
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY Mike G. [Signature] TITLE Field Rep. I DATE May 23, 94

CONDITIONS OF APPROVAL, IF ANY: