Form 3160-5 (June 1990)

UNITED STATES

DEPARTMENT OF THE INTERIOR 11 821 **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

NM 054434-A 6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS								
o not use this form for	proposals to drill or	to deepen or re	eentry to a	different	reservoir.			

D Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation	
1. Type of Well Oil X Gas Well Other Recompletion 11 8 1993	8. Well Name and No.	
2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471).	Yates 6 Federal #2 9. API Well No.	
3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210	30-015-22377 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FNL & 1980' FEL of Section 6-T18S-R26E	Eagle Creek Atoka-Morrow 11. County or Parish, State	
	Eddy Co., NM	

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR O TYPE OF SUBMISSION TYPE OF ACTION	dy co., Mi
	THER DATA
	1
X Recompletion New O	ge of Plans Construction Routine Fracturing Shut-Off ersion to Injection ose Water
Completion	or results of multiple completion or. Well or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to temporarily abandon Morrow completion 8488-8520' by setting a plug in the packer. Will recomplete higher to test the Strawn 8073-8080' and 8100-8107'. After Strawn has been tested, will commingle Strawn and Morrow. Work will proceed as follows:

- 1. Set plug in packer at 8432'. NU & test BOP. Punch holes in tubing just above the packer to allow comunication w/annulus. Swab tubing dry of packer fluid and pull plug. Blow well down to pit until it dies. POOH w/tubing and packer. RIH w/packer with on/off tool and tubing. Set packer at 8450'. Set plug in packer. Release tool and POOH w/tubing.
- 2. RIH w/4" casing gun and perforate 8073-8080' and 8100-8107' w/28 holes (2 SPF).
- RIH w/RBP and packer on tubing. Straddle and acidize Strawn perforations 8073-8107' w/4000 gallons 20% HCL acid with approximately 2700 gallons CO2 and ball sealers.
- 4. Flow and swab back and obtain stabilized flow rate.

NOTE: Additional procedure to commingle Strawn with Morrow will follow.

14. I hereby ceptify that the foregoing is true and correct			
Signed Tusta (lein)	Title	Production Clerk	Date May 27, 1993
(This space for Federal or State office use)			17 ·
Approved by (ORIG, SGOL) JOE G, LAZA Conditions of approval, if any:	Title		Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.