

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

N.M. OIL CON. COMMISSION
P.O. BOX 1980
HOBBS, NEW MEXICO 88240

951

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	7. If Unit or CA, Agreement Designation
2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471	8. Well Name and No. Federal AB Com #5
3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210	9. API Well No. 30-015-22423
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FSL & 660' FWL of Section 21-T18S-R25E (Unit L, NWSW)	10. Field and Pool, or Exploratory Area Penasco Draw Atoka/Penasco Draw Permo Penn
	11. County or Parish, State Eddy Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

10-26-94 - Moved in and rigged up pulling unit. NOTE: Notified Jim Amos with BLM - Carlsbad.

10-27-94 - Nippled down wellhead and nipped up BOP. Worked tubing and attempted to release packer - attempt failed. Ran free point tool and found free point at 6700'. POOH and laid down free point tool. Picked up 1-11/16" cutter. NOTE: Notified Joe Lara w/BLM - Carlsbad. Obtained approval to cut tubing and plug from here. Ran and cut 2-3/8" tubing at 6700'. Rig down wireline. POOH with 2-3/8" tubing. RIH and set 4-1/2" CIBP at 6450'. Dumped 35' of cement on top of CIBP. Rigged down wireline. RIH with 2-3/8" tubing to 3000'. Shut in overnight.

10-28-94 - RIH with 2-3/8" tubing. Tag top of cement. Spotted plug mud from 6410-3000' in 4-1/2" casing. POOH with 2-3/8" tubing. Nippled down BOP and wellhead. Welded 4-1/2" pull nipple. Rigged up casing jacks. Pulled slips and took casing stretch. Free point at 4513'. NOTE: Obtained BLM approval to cut and pull casing from 4513'. Ran and cut 4-1/2" casing with 3-5/8" jet cutter at 4513'. Rigged up casing equipment. POOH with 4-1/2" casing. Rigged down casing equipment. Nippled up BOP and wellhead. Shut in overnight.

10-29-31-94 - RIH with 2-3/8" tubing to 4549'. Spotted 143 bbls plug mud from 4549-2170'. Spot 50 sacks Class C 2% CaCl2 from 4549-4449' (in 7-7/8" hole). POOH with tubing to 3500'. WOC 3 hours. RIH with tubing and tag top of cement at 4418'. POOH with tubing to 4230'. Spot 50 sacks Class C 2% CaCl2 from 4230-4080' (in 7-7/8" hole). POOH with tubing to 3000'.

CONTINUED

14. I hereby certify that the foregoing is true and correct

Signed Rusty Klein Title Production Clerk Date Nov. 2, 1994

(This space for Federal or State office use)

(ORIG. SGD.) JOE G. LARA

Title PETROLEUM ENGINEER

Date 12/6/94

Approved by _____
Conditions of approval, if any: Approved as to plugging of the well bore
Liability under bond is retained until
surface restoration is completed.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

I&E (HOBBS)

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. NM-0487738
2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FSL & 660' FWL of Section 21-T18S-R25E (Unit L, NWSW)	8. Well Name and No. Federal AB Com #5
	9. API Well No. 30-015-22423
	10. Field and Pool, or Exploratory Area Penasco Draw Atoka/Penasco Draw Permo Penn
	11. County or Parish, State Eddy Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other _____	<input type="checkbox"/> Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

CONTINUED FROM PREVIOUS PAGE:

WOC 3 hours. RIH with tubing and tag top of cement at 4030'. POOH with tubing to 2170'. Spot 50 sacks Class C from 2170-2020' (in 7-7/8" hole). POOH with tubing to 1000'. Reverse circulate clean. Shut in overnight. NOTE: Notified Joe Lara w/BLM - Carlsbad of setting plugs.
11-1-94 - RIH with tubing and tagged top of cement at 1980'. Spotted 123 bbls plug mud from 1980-surface. POOH with tubing to 1170'. Spotted 44 sacks Class C 2% CaCl2 from 1170-1020' (in 8-5/8" casing). POOH with tubing to 800'. WOC 3 hours. RIH with tubing and tagged top of cement at 980'. POOH with tubing to 380'. Spotted 27 sacks Class C from 380-280' (in 8-5/8" casing). POOH with tubing to 100'. Spotted 27 sacks Class C from 100' to surface. POOH and laid down tubing. Nippled down BOP. Installed regulation abandonment marker.
PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 10-31-94.

DEC 08 '94

14. I hereby certify that the foregoing is true and correct

Signed [Signature] Title Production Clerk Date Nov. 2, 1994
(This space for Federal or State office use)

Approved by _____ Title _____ Date _____
Conditions of approval, if any: