Form 3160-5 (July 1989) (Formerly 9-331)

CONTACT RECEIVING OFFICE FOR

MIM Roswell District Modified Form No. NH060-3160-4

	В	SUREAU OF L	AND MANAGEMEN	T RECEIVE	ven l"	. LEASE DESIGNATIO	N AND SERIAL NO.	
						NM 0925		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not the this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)						6. IF INDIAN, ALLOTTER OR TRIBE NAME		
	Use "A	PPLICATION FO	THE OF TO deepen or plug OR PERMIT—" for such	back to a different reservoir.	e' i'i c	1		
1.	GAR [,		JAN LO Z 9		UNIT AGREEMENT I		
WELL	WELL XX OT	THER		5 1		OUIT TORKEMENT !	AME	
2. NAME OF OPERATOR				3n. Aren Code & Fin	me No. 6	O. O. PARM OR LEAGE NAME		
HONDO DRILLING CO. 3. ADDRESS OF OPERATOR				(915) 682-940		Wright Federal Com.		
				1 1 2 2 7 002 7 70		WELL NO.	al Com.	
		lidland, TX	79702-2516 I in accordance with any		İ	#2		
See also spa At surface	ace 17 below.)	acton creatty and	i in accordance with any	State requirements.	10	. PIELD AND POOL,	B WILDCAT	
1,980' FNL & 1,980' FEL, Unit G				JAN 3 0 1991	JAN 3 0 1991		North Turkey Track	
						11. SBC., T., R., M., OR BLK. AND SURVEY OR ARMA		
				O. C. D.	!		•	
14. PERMIT NO.		15. ELE	VATIONS (Show whether n	ARTESIA, OFFICE		Sec. 29. T-1	8-S, R-29-E	
30-01	5-22479	[3,490' GR	, A1, GA, EUC.)	12.		1	
16.						Eddy	New Mexico	
- 0,	Chec	:k Appropriat	e Box To Indicate N	lature of Notice, Report,	or Other	Data		
	NOTICE OF	INTENTION TO:		1		REPORT OF:		
TEST WATE	R SHUT OFF	PULL OR AL	TER CASING		[]			
FRACTURE T	TREAT	MULTIPLE (! -	WATER SHUT-OFF		REPAIRING 1	WELL,	
SHOOT OR A	CIDIZE	ABANDON*		FRACTURE TREATMENT SHOOTING OR ACIDIZING	XX	ALTERING C	i	
REPAIR WET	LL.	CHANGE PL	ANE	(Other)		ABANDONME	AI.	
(Other)			=	(NOTE: Report re	erults of m	ultipie completion	on Well	
17. DESCRIBE PRO	DUOSED OR COMPLETE	ED OPERATIONS (C	learly state all pertinen	completion of the	courble (100)	Report and Law for	rm)	
	,					cas for all matheli	of starting any	
12-12-89	Perforate	Atoka Zone	e from 10,490'	to 10,500', 4 shot	s nar	foot Creati		
	and testin	ıg well.		,=== ,	.b pcr	foot. Swabl	orng	
12 10 00								
12-19-90		:11 with 4,	,000 gal 7 1/2%	Mor-Flo Acid. Av	erage :	rate 4 bbl.	ner	
	Acidize well with 4,000 gal 7 $1/2\%$ Mor-Flo Acid. Average rate 4 bbl. per minute, swabbing and testing well.							
1-4-91	Erac vol1		NO 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7					
I 7 71	Frac well with 25,000 gal. of 60 quality Alcofoam in the Atoka Zone, 10,490						0,490'	
	to 10,500', carrying 20,000 pounds of 20/40 Into 2 3/8" tubing at 9.5 bbls per min, average press						down	
	= 370 Edb	ing at 7.5	bors ber min,	average pressure	7,500 1	lb.		
1-5-91	Testing we	esting well, flowing well on 1/2" choke. Venting and burning.						
1-11-91	F							
	18.34 bbl oil - 24 hr test, El Paso Natural Gas Company's line.							
				out out	any 5 1	THE.		
		Ad -						
		•		,				
18. I hereby certif	The aregole	ng is true and cr	orrect		 			
SIGNED (C	Sel Jort		mimes T	mand de				
			TITLE P	resident		DATE Jan. 2	22, 1991	
(This space fo	or Federal or State	office use)						
APPROVED B	IY		TITLE					
CONDITIONS	OF APPROVAL, T	F ANY:				DATE	·	