

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**DISTRICT I**  
P. O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**  
P. O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <b>30-015-22489 22606</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>B-3823-1</b>
7. Lease Name or Unit Agreement Name <b>Empire Abo Unit "I"</b>
8. Well No. <b>283</b>
9. Pool name or Wildcat <b>Empire Abo</b>

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator <input checked="" type="checkbox"/> <b>ARCO Permian</b>	
3. Address of Operator <b>P.O. Box 1089 Eunice, NM 88231</b>	
4. Well Location Unit Letter <b>A</b> : <b>175</b> Feet From The <b>N</b> Line and <b>300</b> Feet From The <b>E</b> Line Section <b>5</b> Township <b>18S</b> Range <b>28E</b> NMPM <b>Eddy</b> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3661' GR</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **Set CIBP & Add Perfs** ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6266' PBD: 6228' CIBP: 6160' PERFS: 6009-6048'

05/06/97: Set CIBP @ 6160'. RIH w/baker Lok-set pkr. Tag CIBP, set pkr. Test plug to 750#.

05/07/97: Perf abo interval 6009-6048' w/1-11/16" strip gun, 2 JSPF, 78 holes.

05/12/97: Acidize perfs 6009-6048' w/1500 gals 15% NEFE acid w/500 SCF/bbl N2. Ran 90 ball sealers. Max press 1860#, min press 1000#, avg press 1400#. AIR 2 BPM, ISIP 1500#. 2-3/8" tbg set @ 5961'. SN @ 5972'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Kellie D. Murrish TITLE: Administrative Assistant DATE: 05/24/99

TYPE OR PRINT NAME: Kellie D. Murrish TELEPHONE NO.: 505-394-1649

(This space for State Use)

APPROVED BY: Jim W. Gurn TITLE: District Supervisor DATE: 5-26-99

CONDITIONS OF APPROVAL, IF ANY: