



207 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210
TELEPHONE (505) 746-3558

RECEIVED

APR 7 1980

O. C. D.
ARTESIA, OFFICE

S. P. YATES
PRESIDENT
MARTIN YATES, III
VICE PRESIDENT
JOHN A. YATES
VICE PRESIDENT
B. W. HARPER
SEC. TREAS.

April 3, 1980

Mr. Bill Gressett
Oil Conservation Commission
Drawer DD
Artesia, New Mexico 88210

Re: State JM Com #1
Unit A, 25-18S-24E


Dear Mr. Gressett:

When the well was put on the line, the pressure kept falling rapidly and we were unable to get a 4 point test on the well.

The well has been shut in and unable to buck line pressure since it was first put on the line.

Yours truly,

YATES PETROLEUM CORPORATION


Eddie M. Mahfood
Engineer

EMM/ob