		All die es	must be from	the outer bounds:	ies of the Sect		
				Lease .			Well No.
	lph Nix Section	Township		Range	County	• Merri	1
etter J	· 34	18 So	n <b>th</b>	26 East		Eddy	
	ocation of Wells	1 10 00	<u>u wi</u>	1 20 1030	<u> </u>		0.00 m
1980	feet from the	South	line and	1980	feet from the	East	line
Level Ele	w. Producing I	Yeso	Po	201	Atoka 1		edicated Acreage:
346	the acreage dedi		I	·····	Atoka-	·····	<u>40 Acie</u>
interest f more ti	and royalty).	different owner	ship is ded	licated to the v	R   well, have the	ECEIV	ll owners been consoli
Yes answer	No If r is "no," list th if necessary.)	answer is "yes e owners and tr	," type of c act descrip	onsolidation tions which ha	ve actually be		ed. (Use reverse side o
	-					•	nitization, unitization pproved by the Commis-
	! - :		<u></u>	1	T		CERTIFICATION
				1	·		
	l I			1		i i	tify that the information con-
	. 1			I		1	n is true and complete to the nowledge and belief.
	1			ł			• • • • • • • • • • • • • • • • • • • •
	4			i	-	Nome	
	+					Position	h. H
	1			1		Company	er
				1	1		h Nix Oil Co.
	1			1	)	Date // /	/ _ 7:_
	1			   <del> </del>	)		•
	1 1 1 1 1 1 1		<u>.</u> ۹	1682	۱  ,	Date /// I hereby ce shown on thi notes of oct	
				/180	۱ •	Date /// I hereby ce shown on thi notes of oct under my sup	rify that the well location s plat was plotted from field wal surveys made by me or pervision, and that the same correct to the best of my
			0,66/		۱ ۶ 	Date // / I hereby ce shown on thi notes of act under my sup is true and knowledge or Date Surveyed Decemb	rilly that the well location s plat was plotted from field wal surveys made by me or pervision, and that the same correct to the best of my ad belief. er 9, 1978
			0000	////	• •	Date // / //	rilly that the well location s plat was plotted from field ual surveys made by me or servision, and that the same correct to the best of my id belief. er 9, 1978 essional Engineer
			0,061	/ <i>fg</i>	۰ •	Date // // // // I hereby ce shown on thi notes of oct under my sup is true and knowledge or Date Surveyed Decemb Registered Prol and/or Land Su	rtily that the well location is plat was plotted from field wal surveys made by me or vervision, and that the same correct to the best of my ad belief. Per 9, 1978 ressional Engineer rveyor