Sivley Federal #2 Page 3

- 9. WELLSITE LAYOUT.
 - A. Only the present well pad and reserve pit area will be used.
- 10. PLANS FOR RESTORATION OF THE SURFACE.
 - A. After finishing drilling and/or completion operations, all equipment and other material not needed for further operations will be removed. The location will be cleaned of all trash and junk to leave the wellsite in as aesthetically pleasing a condition as possible.
 - B. Unguarded pits, if any, containing fluids will be fenced until they have been filled.
 - C. If the proposed well is non-productive, all rehabilitation and/or vegetation requirements of the BLM and USGS will be complied with and will be accomplished as expeditiously as possible. All pits will be filled and leveled within 90 days after abandonment.
 - 11. OPERATOR'S REPRESENTATIVE.

The field representative responsible for assuring compliance with the approved surface use plan is:

Clarence Forister P. O. Box 161 Artesia, NM 88210 (505) 746-3344

12. CERTIFICATION.

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drillsite and access route, that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge, true and correct; and, that the work associated with the operations proposed herein will be performed by Clarence Forister in conformity with this plan and the terms and conditions under which it is approved.

8-23-84

Clarence Forister, Operator

Date