

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

CISF
JP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30.015.22824

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
Empire Abo Unit "L"

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
BP America Production

8. Well No.
133

3. Address of Operator
P.O. Box 1089 Eunice, NM 88231

9. Pool name or Wildcat
Empire Abo

4. Well Location
Unit Letter M : 2 Feet From The 18S Line and 27E Feet From The 800 Line

Section S Township 950 Range W NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Workover ☐

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6135' PBD: 6106' PERFS: 6072-6092' (old), 5658-6036' (new)

11.11.02: MIRUPU. NDWH. NUBOP. RIs pkr. TOH w/prod. tbg.

11.12.02: TIH w/bit & scraper testing tbg in hole to 5000# psi below slips. Tag @ 6101'. TOH.

11.13.02: Perf w/2 JSPF 262 toles total. 5658-76', 5700-11', 5744-67', 5798-5808', 5817-26', 5860-64', 5900-18', 5979-88', 5993-6008', 6032-36'.

11.14.02: Pmp 15 bbls 2% KCL to kill well. TIH w/RBP & pkr. Set RBP @ 6050'. Spot 7.3 bbls 15% HCL. PU & set pkr @ 5552'. Acidize we. w/135.5 bbls 15% HCL w/ additives dropping 400, 1.1 ballsealers. Retrieve RBP & TOH w/BP & pkr.

11.15.02: RIH w/prod. TBG. NDBOP. NUWH.

11.18-21.02: Swab well. Well SI pending engineering evaluation.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Sr. Administrative Assistant DATE 12.16.02

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505.394.1649

(This space for State Use)

APPROVED BY For record only B&B TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DEC 27 2002