Form 3160-5 (December 1989)	UNT D STAT DEPARTMENT OF THE BUREAU OF LAND MA	E INTERIOR	RECEIVEL MAY - 8 1992	FORM APPROVED Budget Bureau No. 1004-0135 Expires September 10, 1990 5. LEASE DESIGNATION AND SERIAL NO.	
SUNDRY NOTICES AND REPORTS ON WELLS OF CONTROL OF CONTR				LC067858	
SUBMIT IN TBIPLICATE				7. IF UNIT OR CA, AGREEMENT DESIGNATION	
1. TYPE OF WELL       Image: Constraint of the state of			<ul> <li>8. WELL NAME AND NO.</li> <li>Empire Abo Unit "M" #133</li> <li>9. API WELL NO.</li> <li>30-015-22833</li> <li>10. FIELD AND POOL, OR EXPLORATORY AREA</li> <li>Empire Abo</li> </ul>		
450 FNL & 1175 FWL (Unit Letter D) 11-18S-27E				11. COUNTY OR PARISH, STATE	
<sup>12.</sup> CHE	CK APPROPRIATE BOX(S) TO I	NDICATE NATURI	OF NOTICE, REP(	DRT, OR OTHER DATA	
TYPE O	TYPE OF SUBMISSION TYPE OF		ACTION		
NOTICE OF INTENT		ABANDONMENT     ABANDONMENT     RECOMPLETION     PLUGGING BACK     CASING REPAIR     ALTERING CASING     Other		CHANGE OF PLANS NEW CONSTRUCTION NON-ROUTINE FRACTURING WATER SHUT-OFF CONVERSION TO INJECTION	
			(NOTE: Report results of inuitiple completion on Well Completion or Recompletion Report and Log form.)		

3. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to recomplete Abo in a higher interval and stimulate.

14. I hereby certify that the foregoing is true and correct		
SIGNED Ken an Somell	Regulatory Coordinator	DATE92
(This space for Federal or State office use)	▶	
		midlas
APPROVED BY	TITLE	DATE 5/0/92
CONDITIONS FOR APPROVAL, IF ANY:		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## **PROPOSED WORKOVER**

## EMPIRE ABO UNIT WELL M-133

Purpose: Plug back watered out Abo zone & perforate & test in Abo Reef

# BRIEF OUTLINE OF PROPOSED WORKOVER

- 1. MIRU PU. NDWH. NU BOP. POH
- 2. Set CIBP above existing perfs. would we
- 3. Perforate 5998-6010 w/ 2 JSPF.
- 4. If well is on vacuum: Swab prior to acidizing.
- 5. If well is not on vacuum: RIH w/ tbg & RET PKR & spot 100 gals 15% HCl.
- 6. Acidize 5998-6010 w/ 1500 gals 15%. Max Press. = 1000 psi.
- 7. If productive then RIH w/ CA. If not productive set a CIBP.
- 8. Perforate 5966-76' w/ 2 JSPF. Continue as with steps 4, 5 & 6
- 9. POH w/ Tbg. & Pkr. RIH w/ CA as per production dept.

## JUSTIFICATION

EAU Well M-133 is located downstructure on the fore reef side of Abo Reef. The well has watered out in the current perforations. Based on the offset producers average rate of 15 BOPD, see the attached production plat, payout of the proposed workover is expected to take 4.3 months.

#### COST ESTIMATE

The estimated gross cost of the workover is \$19,700 based on D. C. Bretches letter of March 3, 1992. Co-owner approval is not required as the expenditure is less than \$25,000.

A - 14 - 92