STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT		•
	TION DIVISION	
P. O. BO	X 2088	Fora C-103
SANTA FE SANTA FE, NEW	MEXICO 87501 BY	Revised 10-1-
U.S.C.S.	RECEIVED DI	Sa. Indicate Type of Lease
LAND OFFICE	ADD . C 1007	
OPERATOR	APR: -6 1987	5. Stole Oll 6 Gas Lease No.
·		E-1286
SUNDRY NOTICES AND REPORTS ON 100 NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DECENT OR PLUE A USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUC	WELLS ADTERIA OFFICE	- Annonnon
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUC	ACL TO A ON LEDIT, CITIC	
		7. Unit Agreement Nome
Name of Operator		
Sol West III		8. Farm or Lease Warme
Address of Cperator	· · · · · · · · · · · · · · · · · · ·	<u> </u>
0. <u>Box 10151, E1 Paso, Texas</u> 79992		
		10. Field and Pool, or Wildcat
UNIT LETTER 660 PEET PROM THE East	LINE AND 1980	Indesignated ON ODD SA
South	FCT	THOM WINGSTHING WIN-GKBG-SA
THE South LINE, SECTION 26 TOWNSHIP 18-S	RANGE 28-E	
15. Elevation (Show whether I		12. County
3459.4' GL		Eddy
Check Appropriate Box To Indicate Na NOTICE OF INTENTION TO:	ature of Notice, Report or SUBSEQU	Other Data ENT REPORT OF:
IF CRM REMEDIAL WORK	-	
PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
LL OR ALTER CASING	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
LL OR ALTER CASING	CASING TEST AND CEMENT JOA	<u> </u>
OTHER	CASING TEST AND CEMENT JOA	ion in Crauburg
	CASING TEST AND CEMENT JOA	ion in Grayburg zone [X
OTHER	CASING TEST AND CEMENT JOA	ion in Grayburg zone [X
	CASING TEST AND CEMENT JOA	ion in Grayburg zone [X
OTHER Describe Proposed or Completed Operations (Clearly state all pertinent detai work) SEE RULE 1103.	CASING TEST AND CEMENT JOA	ion in Grayburg zone [X
Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103.	CASING TEST AND CEMENT JOA	ion in Grayburg zone [X
OTHER Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. 23-Mar -87 Day 1 Completion work started at 12:00 Noon, 2/23/87	CASING TEST AND CEMENT JOA OTHER <u>Attempt</u> <u>complet</u> Is, and give persinent dates, inclu	ion in Grayburg zone X
Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. 23-Mar-87 Day 1 Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X	CASING TEST AND CEMENT JOA OTHER <u>Attempt</u> <u>complet</u> Is, and give persinent dates, inclu	ion in Grayburg zone X
Describe Proposed or Completed Operations (Clearly state all pertinent detail 23-Mar-87 Day 1 Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds)	CASING TEST AND CEMENT JOB OTHER <u>Attempt</u> <u>Complet</u> Is, and give persinent dates, inclu 2-3/8" Larkin head (2,000 ps	ion in Grayburg zone X
OTHER Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. 23-Mar -87 Dav Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with	CASING TEST AND CEMENT JOB OTHER <u>Attempt</u> <u>Complet</u> Is, and give persinent dates, inclu 2-3/8" Larkin head (2,000 ps	ion in Grayburg zone X
OTHER Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. 23-Mar -87 Dav Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with	CASING TEST AND CEMENT JOB OTHER <u>Attempt</u> <u>Complet</u> Is, and give persinent dates, inclu 2-3/8" Larkin head (2,000 ps	ion in Grayburg zone X
Consider the state of the stat	CASING TEST AND CEMENT JOB OTHER <u>Attempt</u> <u>Complet</u> Is, and give persinent dates, inclu 2-3/8" Larkin head (2,000 ps	ion in Grayburg zone X
Considering the second	CASING TEST AND CEMENT JOB OTHER <u>Attempt</u> <u>Complet</u> Is, and give persinent dates, inclu 2-3/8" Larkin head (2,000 ps	ion in Grayburg zone X
 Charle Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. Completion work started at 12:00 Noon, 2/23/87. Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with Picked up and W I H with 2-3/8", 4.7*/ft. tubing. 24-Mar-87 Day 2 Spotted 500 gal. 15% acid at 2260' KB. 	CASING TEST AND CEMENT JOA OTHEN <u>Attempt</u> <u>complet</u> Is, and give persinent dates, inclu 2-3/8" Larkin head (2,000 ps 1 1,000 psig for 15", test OK.	ion in Grayburg zone X
OTHER Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. 23-Mar -87 Dav 1 Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with Picked up and W I H with 2-3/8", 4.7*/ft. tubing. 24-flar-87 Day 2 Spotted 500 gal. 15% acid at 2260" KB. Perforated with on shot per interval as follows (Hyperjet III)	CASING TEST AND CEMENT JOB OTHER <u>Attempt</u> <u>complet</u> Is, and give pertinent dates, inclu 2-3/8" Larkin head (2,000 ps 1 1,000 psig for 15", test OK.	ion in Grayburg zone [X ding estimated date of starting any proposed
 Charle Proposed or Completed Operations (Clearly state all pertinent detail work) see Rule 1103. Completion work started at 12:00 Noon, 2/23/87. Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with Picked up and W I H with 2-3/8", 4.7*/ft. tubing. 24-Mar-87 Day 2 Spotted 500 gal. 15% acid at 2260' KB. Perforated with on shot per interval as follows (Hyperjet III) 2204', 2208' 2211', 2223', 2225', 2227' & 2225' 	2-3/8" Larkin head (2,000 per 1.000 psig for 15", test OK.	ion in Grayburg zone X
Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. Dav 1 Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with Picked up and W I H with 2-3/8", 4.7*/ft. tubing. 24-Mar-87 Day 2 Spotted 500 gal. 15% acid at 2260" KB. Perforated with on shot per interval as follows (Hyperjet III) 2204', 2208' 2211', 2223', 2225', 2227' & 222 W I H with 2-3/8", J-55, 8rd., EU, 4.7*/ft. tubing and packe	2-3/8" Larkin head (2,000 per 1.000 psig for 15", test OK.	ion in Grayburg zone [X ding estimated date of starting any proposed
 Charle Proposed or Completed Operations (Clearly state all pertinent detail work) see RULE 1103. Completion work started at 12:00 Noon, 2/23/87. Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with Picked up and W I H with 2-3/8", 4.7*/ft. tubing. 24-Mar-87 Day 2 Spotted 500 gal. 15% acid at 2260' KB. Perforated with on shot per interval as follows (Hyperjet III) 2204', 2208' 2211', 2223', 2225', 2227' & 222 W I H with 2-3/8", J-55, 8rd., EU, 4.7*/ft. tubing and packe Displaced acid with 12 bbls. 2% KCL water. 	2-3/8" Larkin head (2,000 per 1.000 psig for 15", test OK.	ion in Grayburg zone X
Constant of the second	2-3/8" Larkin head (2,000 per 1.000 psig for 15", test OK.	ion in Grayburg zone [X ding estimated date of starting any proposed
 Charle Proposed or Completed Operations (Clearly state all pertinent detail work) see Rule 1103. Completion work started at 12:00 Noon, 2/23/87. Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with Picked up and W I H with 2-3/8", 4.7*/ft. tubing. 24-Mar-87 Day 2 Spotted 500 gal. 15% acid at 2260" KB. Perforated with on shot per interval as follows (Hyperjet III) 2204', 2208' 2211', 2223', 2225', 2227' & 222 W I H with 2-3/8", J-55, 8rd., EU, 4.7*/ft. tubing and packe Displaced acid with 12 bbls. 2% KCL water. Swabbed 24 bbls. load water; no show of oil or gas. 	2-3/8" Larkin head (2,000 per 1.000 psig for 15", test OK.	ion in Grayburg zone [X ding estimated date of starting any proposed
 Charlet (LAS) Describe Precosed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with Picked up and W I H with 2-3/8",4.7*/ft. tubing. 24-Mar-87 Day 2 Spotted 500 gal. 15% acid at 2260' KB. Perforated with on shot per interval as follows (Hyperjet III) 2204', 2208' 2211', 2223', 2225', 2227' & 222 W I H with 2-3/8", J-55, 8rd., EU, 4.7*/ft. tubing and packe Displaced acid with 12 bbls. 2% KCL water. Swabbed 24 bbls. load water; no show of oil or gas. 25-Mar-87 Day 3 Acidized with 1500 gal. 15% NEFE. 	CASING TEST AND CEMENT JOB OTHER Attempt complet Is, and give persinent dates, inclu 2-3/8" Larkin head (2,000 ps 1 1,000 psig for 15", test OK. 19' KB (7 holes). r to 2153' KB.	ion in Grayburg zone [X
 Charlet (Kis) Describe Preposed or Completed Operations (Clearly state all pertinent detail work) see Rule 1103. Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with Picked up and W I H with 2-3/8", 4.7*/ft. tubing. 24-Mar-87 Day 2 Spotted 500 gal. 15% acid at 2260' KB. Perforated with on shot per interval as follows (Hyperjet III) 2204', 2208' 2211', 2223', 2225', 2227' & 222 W I H with 2-3/8", J-55, 8rd., EU, 4.7*/ft. tubing and packe Displaced acid with 12 bbls. 2% KCL water. Swabbed 24 bbls. load water; no show of oil or gas. 25-Mar-87 Day 3 Acidized with 1500 gal. 15% NEFE. Swabbed 17 bbls. load water, no show of oil or gas. 	Continued	ion in Grayburg zone [X
 Charlet P(Aks Describe Preposed or Completed Operations (Clearly state all pertinent detail work) see Rull e 1103. Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with Picked up and W I H with 2-3/8",4.7*/ft. tubing. 24-Mar-87 Day 2 Spotted 500 gal. 15% acid at 2260' KB. Perforated with on shot per interval as follows (Hyperjet III) 2204', 2208' 2211', 2223', 2225', 2227' & 222 W I H with 2-3/8", J-55, 8rd., EU, 4.7*/ft. tubing and packe Displaced acid with 12 bbls. 2% KCL water. Swabbed 24 bbls. load water; no show of oil or gas. Swabbed 17 bbls. load water, no show of oil or gas. 	Continued	ion in Grayburg zone [X
 Charlet P(Aks Describe Preposed or Completed Operations (Clearly state all pertinent detail work) see Rull e 1103. Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with Picked up and W I H with 2-3/8",4.7*/ft. tubing. 24-Mar-87 Day 2 Spotted 500 gal. 15% acid at 2260' KB. Perforated with on shot per interval as follows (Hyperjet III) 2204', 2208' 2211', 2223', 2225', 2227' & 222 W I H with 2-3/8", J-55, 8rd., EU, 4.7*/ft. tubing and packe Displaced acid with 12 bbls. 2% KCL water. Swabbed 24 bbls. load water; no show of oil or gas. Swabbed 17 bbls. load water, no show of oil or gas. 	Continued	ion in Grayburg zone [X
 Charles Piccosed or Completed Operations (Clearly state all pertinent detail work) see RULE 1103. 23-Mar-87 Dav 1 Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with Picked up and W I H with 2-3/8", 4.7*/ft. tubing. 24-Mar-87 Day 2 Spotted 500 gal. 15% acid at 2260' KB. Perforated with on shot per interval as follows (Hyperjet III) 2204', 2208' 2211', 2223', 2225', 2227' & 222 W I H with 2-3/6", J-55, 8rd., EU, 4.7*/ft. tubing and packe Displaced acid with 12 bbls. 2% KCL water. Swabbed 24 bbls. load water; no show of oil or gas. 25-Mar-87 Day 3 Acidized with 1500 gal. 15% NEFE. Swabbed 17 bbls. load water, no show of oil or gas. 	Continued	ion in Grayburg zone [X
 OTHER Describe Proposed or Completed Operations (Clearly state all pertinent detail work) see RULE 1103. Completion work started at 12:00 Noon, 2/23/87. Welded on an 8-5/8" casing extension; installed 8-5/8" SO X Installed 8" X 900 series BOP (2-3/8" rams and blinds). Closed blind rams; pressure tested casing, well head etc. with Picked up and W I H with 2-3/8", 4.7*/ft. tubing. 24-Mar-87 Day 2 Spotted 500 gal. 15% acid at 2260' KB. Perforated with on shot per interval as follows (Hyperjet III) 2204', 2208' 2211', 2223', 2225', 2227' & 222 W I H with 2-3/8", J-55, 8rd., EU, 4.7*/ft. tubing and packe Displaced acid with 12 bbls. 2% KCL water. Swabbed 24 bbls. load water; no show of oil or gas. 25-Mar-67 Day 3 Acidized with 1500 gal. 15% NEFE. 	Continued	ion in Grayburg zone [X

26-Mar-87 Day 4

- -- Swabbed well dry, recovered 400' heavily oil cut load water. 27-Mar-87 Day 5
- Fracture treated well with 20,000 gal. 2% KCL gelled water 16,500# 20/40 sand and 15,000# 12/20 mesh sands.
 28-Mar-87 Day 6

أتناسب شيار ليابده

- -- Opened well to fractank; flowed 150 bbls. load waater in 9 hrs., slight gas flare. 29-Mar-87 Day 7
- -- Flowed well to frac tank; recovered 15 bbls. load with slight gas flare. 30-Mar-87 Day 8
- -- Flowed and swabbed for 10 hrs.; recovered 110 bbls. fluid, 20 to 30% oil. [31-Mar-87 Day 9]
- -- Flowed and swabbed for 12 hrs.; recovered 90 bbls. fluid, 30 to 35% oil 1-Apr-87 Day 10
- -- Flowed and swabbed for 3 hrs.; recovered 25 bbls. fluid, 60 to 90% oil.
- -- Final report until surface equipment set and potential test completed.