		••	
	UNI ED STATES ARTMENT OF THE INTERIOR AU OF LAND MANAGEMENT		Prawer DD Prawer DD Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM. 0.2056
Do not use this form for propos	DTICES AND REPORTS ON W als to drill or to deepen or reentr "ION FOR PERMIT—" for such p	ry to available termuraservoir	
	SUBMIT IN TRIPLICATE	FFR 2	7. If Unit or CA, Agreement Designation
1. Type of Well Oil X Gas Well Well Other		. 26 2 2 1995	8. Well Name and No.
2. Name of Operator YATES PETROLEUM CORPOR	ATION (505)	748-1491 N.M: -	North Turkey Track MU Fed 9. API Well No. Com #1
3. Address and Telephone No. 105 South 4th St., Art	esia, NM 88210	Shad, New Mexico	30-015-23136 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M.,	or Survey Description) Section 33-T18S-R29E (U	nit C)	No. Turkey Track Morrow 11. County or Parish, State Eddy Co., NM
12. CHECK APPROPRIA	TE BOX(s) TO INDICATE NAT	URE OF NOTICE, REP	ORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTIO	N .
Notice of Intent Subsequent Report Final Abandonment Notice	Clearly state all pertinent details, and give pertinent	etion RECEIVE Back MAR 1 0 199	Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

2-7-95 - Moved in and rigged up pulling unit. Bled tubing and annulus down. Nippled down wellhead and installed BOP. Unset packer. Dropped down and unset RBP. Pulled up and reset RBP at 10179' and tested to 2000 psi for 5 minutes. Pulled up and set packer at 9679'. Tested down tubing to 2000 psi. Removed BOP and nippled up wellhead. Opened bypass on packer and spotted 1000 gallons 15% NEFE acid to end of packer. Closed bypass and rigged up wireline. TIH with 1-11/16" tubing gun and perforated 9781-9791' w/21 .38" holes (2 SPF - Cisco Lime). Packer came loose and started circulating around annulus. TOOH with tubing gun and rigged down wireline. Reset packer and try to pressure up on tubing. Continues to circulate around annulus. Nippled down wellhead and installed BOP. Unset packer. Reversed acid out of hole. TOOH with 2-7/8" tubing and packer. TIH with packer and tubing. Set packer at 9679'. Removed BOP and nippled up wellhead. Tested packer down tubing to 1800 psi for 10 minutes. Swabbing.

2-8-95 - Flare well to pit and swabbed. Acidized perforations 9781-9791' (Cisco Lime) with 2000 gallons 15% NEFE acid. Swabbing.

2-9-95 - Swabbed and flowed. Shut well in.

2-10-95 - Installed tree saver and acidized perforations 9781-9791' w/20000 gallons 15% NEFE acid. Removed tree saver and opened well and flowed to tank.

2-11-13-95 - H	Flowed and	swabbed.	Shut	well	in.	Released	to	production	department.	

14. I hereby certify that the foregoing is frue and correct Signed Tusty Much	Title Production C	Date Date Feb. 16, 1995
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	J. Jala MAP 7 1005
or representations as to any matter within its jurisdiction.	and willfully to make to any department	ent or agency of the United States any false, fictititus or foundulent statements