

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	
LAND OFFICE	
OPERATOR	☒

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

OIL
WELL ☐

GAS
WELL ☒

OTHER ☐

AUG 11 1980

Name of Operator

Harvey E. Yates Company

Address of Operator

P. O. Box 1933, Roswell, New Mexico 88201

Location of Well

UNIT LETTER F 1980 FEET FROM THE North 1980 FEET FROM
THE West 13 LINE, SECTION 18S TOWNSHIP 28E RANGE NMPM.

5a. Indicate Type of Lease

State ☒

For ☐

5. State Oil & Gas Lease No.

B-11594-3

7. Unit Agreement Name

8. Farm or Lease Name

Travis 13 State

9. Well No.

1

10. Field and Pool, or Wildcat

Wilcat Morrow

15. Elevation (Show whether DF, RT, GR, etc.)

3604.5 GL

12. County

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOB ☒

OTHER Plug off lost circ. zone ☒

OTHER ☐

1. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/28/80 Depth-5250'. Drlg w/fresh water, Lime & Shale. Started losing fluid @5050'. 25% returns.

7/29/80 Depth-5794'. Drlg w/fresh water, lime & shale. Losing 40 bbl fluid/hr. Mixing LC material.

7/30/80 Depth-6369'. Drlg w/fresh water, lime & shale. POH. RUN DP O/E to 6089'. Mixed 300 sx C1 "C" thix set w/10# gilsonite, 1/4 lb flocele & 2% CaCl. Job complete @ 2:45 a.m. 7/3/180. WOC Pull DP OOH.

7/31/80 Depth-6623' WOC, lime & shale. TIH w/ DP O/E to 4250'. Mx 100 sx C1 "C" Thix set w/10# gilsonite, 1/4# flocele, 2% CaCl. Job complete 11:30 p.m. POH. Go in hole to T/cement @ 4292'.

8/01/80 Depth-6630'. Drlg w/fresh water. Drld. cement plug 4292' to 6148' w/full returns

8/05/80 Depth-8109'. On TOH for bit & Yellow jacket. Tested BOP stack to 1500 psi. O.K.

6. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

Paul J. Hardee

TITLE

Engineer

DATE

August 8, 1980

APPROVED BY

W. A. Gressitt

TITLE

SUPERVISOR, DISTRICT II

DATE

AUG 12 1980

CONDITIONS OF APPROVAL, IF ANY: