

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	1
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION **RECEIVED**

P. O. BOX 2008

SANTA FE, NEW MEXICO 87501

SEP 15 1980

O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-79

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
ST-647	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REEVALUATE PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name Illinois Camp NN St.
3. Address of Operator 207 S. 4th St., Artesia, NM 88210		9. Well No. 1
4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 30 TOWNSHIP 18S RANGE 28E N.M.P.M.		10. Field and Pool, or Wildcat Und. Illinois Camp Mor.
11. Elevation (Show whether DF, RT, CR, etc.) 3546' GR		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER Perforate & acidize ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 10730'- WIH w/casing gun on wireline and perforated 10548-10561' w/10 .50" holes as follows: 10548, 49, 52, 53, 56, 57, 58, 59, 60 & 61'. Ran 338 joints of 2-3/8" EUE N-80 tubing, 4-1/2" x 2-3/8" Guiberson full-bore on-off tool, 2-3/8" x 1.81" Baker "F" Nipple and Guiberson Uni VI packer. Set packer at 10518'. Swabbed and recovered no fluid w/gas TSTM.
Acidized perforations 10548-10561' with 2000 gallons 7-1/2% MS acid and N₂. Recovered load. Fluid level 6200' from surface. Swabbed well.

TD 10730' Pulled tubing and packer. WIH and set CIBP at 10500'. Dumped 35' of cement on top of CIBP. WIH w/casing gun on wireline and perforated 10350-10414' w/12 .34" holes as follows: 10350, 51, 52, 57' (4 holes) and 10392, 93, 98, 10401, 03, 09, 13 & 14' (8 holes). RIH w/Guiberson Uni VI packer on 2-3/8" tubing. Set packer at 10298'.

PBTD 10465' Preparing to acidize perforations 10350-10414'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Albert R. Stall TITLE Engineer DATE Sept. 11, 1980

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE SEP 17 1980

CONDITIONS OF APPROVAL, IF ANY: