STATE OF NEW ME			
	OIL CONSERVATION DIVIS		
DISTRIBUTION	P. O. BOX 2088 RECEIV		2
SANTA PE		Revised 1	
}	SANTA FE, NEW MEXICO 8750)1	
U.S.O.S.		5a. Indicate Type of Lease	
LAND OFFICE		1981 State X Foo	\square
OPERATOR	 	5. State Oil 6 Gas Lease No.	
0.5.1.1.0.1	D.C. (State 647	
	CUNDEN NOTICES AND DEPOSITE ON WELL AFIEND		\overline{m}
DO NOT USE THIS FOR	SUNDRY NOTICES AND REPORTS ON WELLS FIELD ON THE PROPOSALS TO PAILL ON TO DEEPEN OF PLUG BACK TO A DIFFERENT A		///,
	APPLICATION FOR PLANIT - " (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name	777,
01L GAS	DOTHER. P&A	r, one represent theme	
ame of Operator		8. Farm or Lease Name	····
Yates Pe	troleum Corporation	Illinois Camp NN Sta	nt o
dress of Operator		9, Well No.	110
•	th St., Artesia, NM 88210	3, weir 110.	
cation of Well		10. Field and Pool, or Wildcat	Tind
	660 South 10		
UNIT LETTER	660 South	980 Illinois Camp Morrow	v -
			////
West	NE, SECTION TOWNSHIP 185 RANGE	<u>зе</u> "мрм. ())))))))))))))))))))))))))))))))))))	())
			///.
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County	\overline{M}
	3558' КВ	Eddy	////
	Check Appropriate Box To Indicate Nature of Notice,	Report of Other Data	<u></u>
	E OF INTENTION TO:	SUBSEQUENT REPORT OF:	
ORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	ſ
PORARILY ABANDON	COMMENCE DRILLING		
L OR ALTER CASING	CHANGE PLANS CASING TEST AND CE		n L <u>a</u>
			
THER			L_
Jescribe Proposed or Com	plotod Operations (Clearly state all pertinent details, and give pertine.	nt dates, including estimated date of starting any pro	posed
work) SEE AULE 1903.			-
TD 107201 D.11	od tubing frankru (L. OTDD - 1. 1)		
<u>10 10730</u> - Pull	ed tubing & packer. Set CIBP on wireline a	it 8300' w/35' cement on plug.	
Cut casing at 7	900'. Layed down casing. Spotted cement p	lugs as follows:	
Plug #1	7935-7835' with 35 sacks Class "C" Neat.		
Plug #2	5425-5325' with 35 sacks Class "C" Neat.		
Plug #3	2988-2888' with 35 sacks Class "C" Neat.		
Plug #4	2076-1920' with 40 sacks Class "C" Neat.		
· - ug " -			
	Tagged cement at 1920'.		
P1	Surface to $201 - 10$ 1 or that -		
Plug #5	Surface to 30' w/10 sacks Class "C" Neat	. Heavy mud between plugs.	
Installed June L	olo mankon Comfree of 11.1		
installed dry N	ole marker. Surface will be restored.		
hereby certify that the in	formation above is true and complete to the best of my knowledge and b	pelief.	
	$\dot{\phi}_1$		
o,	Engineering Sec	retary 7-16-81	
6			
	22000 20		
	DURCHIELD TITLE OIL AND GAS INSPEC	TOR JUL 2 2 198	1
VED BY Mires	$\mathbf{X}_{\mathbf{r}}$	1794 DATE JUL 2 2 198	1

• •