

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION

2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO.

30-015-23647

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

LC-060888

7. Lease Name or Unit Agreement Name:

BALLARD GRAYBURG SAN ANDRES UNIT  
TRACT 24

8. Well No.

5

9. Pool name or Wildcat

LOCO HILLS ON GB SA

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-104) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Anadarko Petroleum Corp.

3. Address of Operator

P.O. Box 2497 Midland, TX 79702

4. Well Location

Unit Letter 0 : 450 feet from the SOUTH line and 2100 feet from the EAST line

Section 5 Township 18S Range 29E NMPM County EDDY

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3531.4 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. MIRU. SET CIBP @ 2350'.

2. TIH W/TBG. CIRC W/9.5# SALT GEL MUD.

3. CIRC 25 SX CMT ON PLUG. WOC & TAG.

4. SET 25 SX CL "C" FROM 860 - 500' (BASE SALT) - <sup>T<sub>2</sub></sup>

5. SET 30 SX CL "C" FROM 400' - SURFACE. TAG.

6. CUT OFF WH.

7. INSTALL MARKER.

← Place 60' of cmt between 4 1/2" & 8 1/2" CSG - 0'-60'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sabra Wallum TITLE ENGINEERING TECHNICIAN III DATE 11/27/02

Type or print name SABRA WALLUM

Telephone No. 915/683-0534

(This space for State use)

APPROVED BY [Signature] TITLE Wild [Signature] DATE DEC 10 2002

Conditions of approval, if any: