

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|   |
|---|
| WELL API NO.<br>30-015-23669  |
| 5. Indicate Type of Lease<br>STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No.  |
| 7. Lease Name or Unit Agreement Name<br>Young PJ  |
| 8. Well No.<br>1  |
| 9. Pool name or Wildcat<br>Atoka San Andres   |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☐ OTHER PLUGGED & ABANDONED

2. Name of Operator  
YATES PETROLEUM CORPORATION

3. Address of Operator  
105 South 4th St., Artesia, NM 88210

4. Well Location  
Unit Letter G : 2310 Feet From The North Line and 1650 Feet From The East Line  
Section 27 Township 18S Range 26E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO:                        |   | SUBSEQUENT REPORT OF:                               |  |
|--|---|---|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>                 |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  |   | CASING TEST AND CEMENT JOB <input type="checkbox"/> |  |
| OTHER: <input type="checkbox"/>                |   | OTHER: <input type="checkbox"/>                     |  |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-17-95 - Notified Mike with OCD - Artesia of commencing plugging operations. Moved in and rigged up pulling unit. Nippled down pumping unit. POOH with rods and pump. Nippled up BOP. TOOH with tubing, seating nipple, perf sub and mud anchor. Rigged up wireline. TIH with 4-1/2" CIBP and set at 1550'. Rigged down wireline. TIH with 2-7/8" tubing and tagged CIBP. Spotted 25 bbls plug mud from 1550' to surface. Mixed and pumped 5 sacks Class C cement from 1550-1475' (in 4-1/2" casing). POOH with tubing to 1170'. Mixed and pumped 25 sacks Class C cement from 1170-809' (in 4-1/2" casing). POOH with tubing to 90'. Mixed and pumped 10 sacks Class C cement from 90' to surface. POOH with tubing. Nippled down BOP. Cleaned location and installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 2-16-95.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 2-23-95  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)  
APPROVED BY Ken Livingston TITLE F.R. DATE 4-28-95  
CONDITIONS OF APPROVAL, IF ANY: