

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

LEASE DESIGNATION AND SERIAL NO.

NM - 025503

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR HANSON OIL CORPORATION		7. FARM OR LEASE NAME Ginsberg Federal	
3. ADDRESS OF OPERATOR P. O. BOX 1515, ROSWELL, NEW MEXICO 88201		9. WELL NO. #17	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FNL & 990' FEL NE 1/4 NE 1/4		10. FIELD AND POOL, OR WILDCAT Shugart	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26, T. 18S, R. 30E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3459.8		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

RECEIVED
FEB 16 1982
O. C. D.
ARTESIA OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING ☒

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See Attached
Two (2) pages

RECEIVED
FEB 20 1982
OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *Peter W. Chester*

TITLE Production Analyst

DATE 2/25/82

(This space for Federal or State office use)

APPROVED BY **PETER W. CHESTER**
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JUN 14 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

SUNDRY NOTICES AND REPORTS ON WELLS

FORM 9-331

GINSBERG FEDERAL #17
Sec.26, T.18S, R.30E
Eddy County, New Mexico

Page 1

- 1-12-82 Rn csg scraper to TD 3456', pull tbg back out. RU GeoVan. Rn logs (Gamma Ray and Collar Locator; Cement Bond Log).
Perf 3390 - 3398', 2 JSPF
- 1-14-82 PBTD 3456'
Rn tbg & RTTS pkr in hole to 3410', spot one BA, pull one stnd & set pkr @3350', press up & broke fm @2100#. Acidize w/850 gal 15% MCA, avg press-1300 psi, 3.1 BA/min. ISIP - 1100#
- 1-18-82 Perf 3354 - 3362', 2JSPF
Spot 50 gal acid. Break fm w/wtr @1200#. Acidize w/1000 gal NEFE, 15% @4.4 BPM, 1400#.
- 1-20-82 Frac w/20000 gal @15000 gal gel wtr & 5000 CO₂, 195 sx snd. Pmpd 5000 gal pad @17.5 BPM, 1960#. Pmpd 3000 gal, 1/2#/gal, 20/40 snd @17 BPM @2480# TP. Pmpd 3000 gal 1#/gal, 20/40 snd, 17 BPM, 2510 psi. 3000 gal, 1-1/2# per gal, 20/40 snd @17.2 BPM @2510 psi. Pmpd 3000 gal, 2#/gal, 20/40 snd @17.2 BPM, @2500 psi TP. Pmpd 3000 gal, 1-1/2#, 10/20 snd @17.2 BPM, 2470# TP. Pmpd 950 gal flush @17.1 BPM @2450# TP. ISIP - 1260#
- 1-25-82 Perf 3120 - 3128', 2 JSPF
- 1-26-82 Broke dn fm @2400#. Rn 1000 gal NEFE acid @4.4 BPM @1400#. Pmp 5000 gal pad @3160 psi. Pmp 6500 gal of 1/2#, 20/40 snd/gal @3260 psi; 8000 gal 1# snd/gal @3760 psi, 800 gal, 1/2# snd/gal @4200 psi. ISIP - 2160#
- 1-28-82 Perf 3074 - 3082', 2 SPF
Spot 50 gal acid. Brk fm w/wtr @1800#. Acidize w/1500 gal NEFE, 15% @3-1/2 BPM, 1250 psi. ISIP - 850#
- 1-30-82 TP 150, RU Haliburton to frac. Frac w/15000 gal gel wtr, 5000 CO₂. Pmp 5000 gal pad @2460 psi, pmpd 3000 gal 1/2#, 20/40 snd/gal @2740 psi, pmpd 3000 gal, 1#/gal, 20/40 snd @3300#. Pmpd 3000 gal 1-1/2# snd/gal, 20/40 snd @3650 psi. Pmpd 3000 gal, 2#/gal, 20/40 snd @3200 psi. Pmpd 3000 gal 1-1/2#/gal, 10/20 snd @2970 psi. Pmpd 1100 gal of flush @2830 psi. ISIP - 1370#

SUNDRY NOTICES AND REPORTS ON WELLS

FORM 9-331

GINSBERG FEDERAL #17
Sec.26, T.18S, R.30E
Eddy County, New Mexico

Page 2

2-01-82 Perf 2648 - 2658'

2-02-82 Acidize w/1500 gal NEFE, 15%. Pmpd 3.6 BPM @1866 psi. ISIP - 1600#

2-04-82 Perf 2158 - 2168'
Spot 50 gal acid. Brk fm @2500# w/wtr. Acidized w/1500 gal NEFE acid,
15% @4.7 BPM @1900 psi. ISIP - 1300#

2-08-82 Perf 2082 - 2090'

2-10-82 Sptd 50 gal acid. BDF @2800#. Pmpd 16 BA @1900#. ISIP - 0

2-11-82 Pull BP, RTTS pkr and tbg. Rn 109 jts 2-7/8", rn 135 jts 3/4" rods,
1-1/2" pmp.