N.M.O.C.D. COPY	▲
Form 9-331 Dec. 1973	Form Approved. Budget Bureau No. 42-R1424
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE LC 050906
CISE GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME RECEVED Ballard Grayburg San Andres Unit
reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME Tract No. 5 JUN 2 6 1981
1. oil gas well well other	9. WELL NO.
Anadarko Production Company /	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Loco Hills-Queen-Grayburg-San Andres
P. O. Box 67, Loco Hills, New Mexico 88255 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 400' FSL & 2130' FEL, Sec. 8, T18S	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 8 - 185 - 29E
AT SURFACE: Same R29E	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH:	Eddy New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3507.3 GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	· · · · · ·
TEST WATER SHUT-OFF	(NOTE: Report reselfs of multiple completion of each of multiple completion of each of the second state of
(other) Spud, Drill TD, set csg X	ROSWELL, NEW MEXICO
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	directionally drilled, give subsurface locations and

1. Moved in and rigged up rotary tools.

 Spudded 12¹/₂" hole @ 6:15 PM 6-7-81. Drilled to 355¹ - did not lose circulation. Set 8-5/8" casing w/casing shoe @ 346¹ KB & Halliburton cemented w/250 sx Class H w/27. CaCL. PD @ 4:30 AM 6-8-81 - circulated 25 sx to pit. Installed Series 900 Double Ram Hydraulic Blowout Preventor; pressure tested casing & BOP to 1000# psi.
Drilled shoe on 8-5/8" casing w/7-7/8" bit after 19 hours WOC. Drilled to 2830¹ &

- Drilled shoe on 8-5/8" casing w/7-7/8" bit after 19 hours WOC. Drilled to 2830" ran GR/Compensated Neutron Log. Attempted to run other O. H. logs but logging tools failed.
- 4. Ran 5½", 15.5# casing with casing shoe @ 2829' KB. Halliburton cemented with 325 sx Halliburton Lite & tailed in with 250 sx Class H did not circulate cement. Bennett Wireline Company found cement top @ 1700'.
- 5. Plan to perforate 5¹/₂" casing @ top of cement (1700') and circulate cement to surface. <u>Note:</u> 5¹/₂" casing was substituted for 4¹/₂" casing. Will file appropriate reports upon completion of well. Subsurface Safety Valve: Manu. and Type _______ Set @ ______ Ft.

		TLE Area Supervison	_ DATEJune 16, 1981	
CONDITIONS O	APPROVAL, IF ANY:	TILE	DATE	
		prior to spudding & cementing $8-5/8"$ casing. I prior to cementing $5\frac{1}{2}"$ casing.		
	U.S. GEOLOGICAL SURVEY	e Instructions on Reverse Side		