Form 9-331 (May 1963)	DEPART	UNI <sup>-</sup> O STATE MEN1 OF THE I		SUBMIT IN TRIPL' (Other instructions verse Bide)	'E• re-	Form approve Budget Burea 5. LEASE DESIGNATION	u No. 42-R1424.
013	F	GEOLOGICAL SUR	VEY			LC-029415-I	3
(Do not use	UNDRY NO this form for prop Use "APPLIC	TICES AND REPC osals to drill or to deepen CATION FOR PERMIT-"	DRTS ON or plug back for such propo	WELLS COMMI to a different gaservoir.	552 10	6. IF INDIAN, ALLOTTEE	0.0.7
1. OIL X GAS WELL WE	LL OTHER			Mi OID DD NM Drawer DD NM Artesia.		7. UNIT AGREEMENT NA	ARTESIA, OFFICE
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different servoir. Use "APPLICATION FOR PERMIT_" for such proposals.) I. OIL S GAS WELL OTHER 2. NAME OF OPERATOR NCtODING COMPLETING OTHER COMPLETING COMPLETI						8. FARM OR LEASE NAME	
WILLIAM A. & EDWARD R. HUDSON 🗸						Puckett "B"	
3. ADDRESS OF OPERATOR						9. WELL NO.	
Box #198, Artesia, New Mexico 88210						30	
4. LOCATION OF WEL	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*					10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface 2615' from south and 380' from east lines of						Maljamar (G-SA)	
Section 25-17S-31E					-	11. SEC., T., R., M., OR BLK. AND	
		00		-170-511		SURVEY OR ABEA	
						Sec. 25-17S-	-31E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)				[-	12. COUNTY OR PARISH 13. STATE		
						Eddy	New Mexico
16.	Check A	ppropriate Box To Ind	dicate Natu	re of Notice, Report, o	or Ot	her Data	
NOTICE OF INTENTION TO: SUBSEQU					BSEQUE:	NT REPORT OF:	
TEST WATER SH	UT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING W	ELL
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT	X	ALTERING CA	
SHOOT OR ACIDIZ		ABANDON*		SHOOTING OR ACIDIZING		ABANDONMEN	
REPAIR WELL		CHANGE PLANS		(Other)	اليــــــ		
(Other) (Note: Report results Completion or Recomplet							

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

On 1-11-82 acidized perforations at 3847-75 with 2,000 gals. 20% acid containing 25 gals. ProtexAll and 25 gals. corrosion inhibitor. Maximum pressure 3300 psi., and minimum was 2,600 psi. at 1.5 BPM.

On 1-15-82 with retrievable bridge plug at 3790 and packer at 3695', acidized perfs at 3721-66 with 2,000 gals. 20% acid containing ProtexAll and corrosion inhibitor, in 2 stages with 200# rock salt plug between stages. Formation broke at 2500 psi. and treated at 1800 psi. at 2 BPM.

On 1-19-82, treated perfs at 3721-66 with 6,000 gals. 20% acid + 10,250 gals. Redi-frac gel + 8,000# FLA-100 sand + 55 gals. ProtexAll + 55 gals. corrosion inhibitor, in 2 stages, using 100# benzoic acid flakes + 100# rock salt plug between stages. First stage treated at 2400 psi. at 5 BPM. Second stage treated at 2900 psi. at 5 BPM. ISIP - 2100 psi.

- They

	PIER CARANTER 1962
18. I hereby certify that the foregoing is true and correct	COLOCIES AND
SIGNED MALL TITLE Consulting Engineer	Jan. 25, 1982
(This space for Federal or State affice PSM AC	<u> </u>
APPROVED BY TITLE CONDITIONS OF APPEOVAL, IF ANY: FEB 2 1022	DATE
U.S. GEOLOGICAL SURVEX ROSWELL, NEW TARXICO	
ROSWELL, NEW TAEXILLY	