RECEIVED

NO. 2 DINKUS
P & A REQUIREMENTS

SEP 23 1981

O. C. D. ARTESIA, OFFICE

Received verbal approval from Bill Gressett for following plugging procedure:

Load hole with mud laden fluid.

```
      Spot 35 sx plug
      8700'-8800'
      -
      Morrow

      Spot 35 sx plug
      8480'-8580'
      -
      Atoka

      Spot 35 sx plug
      6850'-6950'
      -
      Cisco

      Spot 35 sx plug
      5380'-5480'
      -
      Wolfcamp

      Spot 35 sx plug
      4080'-4180'
      -
      Abo

      Spot 35 sx plug
      2000'-2100'
      -
      Glorieta

      Spot 35 sx plug
      1100'-1200'
      -
      8 5/8" shoe

      Spot 35 sx plug
      250'- 350'
      -
      13 3/8" shoe

      10 sx surface
      plug w/marker
```

Call Commission to notify them before spotting plugs.