STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES ACCEIVED	3		
DISTRIBUTION			
SANTA FE			
FILE	I_{I}		
U.S.G.S.			
LAND OFFICE			
OPERATOR	17	1	

OIL CONSERVATION DIVISION

DISTRIBUTION			P. O. BOX 2088					Form C-103			
SANTA FE	1		SANTA FE, NEW MEXICO 87501						Kevised	1 10-1-78	
FILE	_ _/ =							5a, Indicate Type of Lease			
U.S.G.S.							-	State	١	00 X	
DERATOR	- , 						}		Gas Lease No		
(DO NOT USE THIS F.	SUNI	DRY NOTICES	S AND REPORT	IS ON V	VELLS	RECEIVE HT RESERVOIR.	0				
OIL X GAS WELL		OTHER+			0	CT 2 9 19	181	7, Unit Agree	ment Name		
Name of Operator								8. Form or Lease Name Platt PA			
Address of Operator 207 South 4t	h St.	, Artesia,	NM 88210		A	RTESIA, OFFIC	CE	9. Well No.	7		
						<u> </u>		10. Flold and	Pool, or Wilde	at	
UNIT LETTER		990	ET PROM THESC	outh	LINE AND	1650	EET FROM	Atoka	Yeso	77777	
West			qlhenwor				[
THE	LINE, SEC	T10H ZO	чінеимот	.03	MANGE		- NMPM.				
		15	, Elevation (Show) 3315		F, RT, GR, etc	.)	,	12. County	,,,,,,,,,,,	1111	
ZIIIIIIIIII	77777	TITITIA						Eddy		77777	
NOTI		k Appropriate INTENTION	Box To India	cate Na	ture of Not				7		
NOT	CC OF	1141 E141 1014	10:			20825	QUENT	REPORT (Jr:		
CREORM REMEDIAL WORK	7		PLUG AND ABAND	on []	REMEDIAL WORK		\Box	Aı	TERING CASING		
EMPORARILY ABANDON	Ī				COMMENCE DRIL		লৈ		UG AND ABANDON	, H	
LL OR ALTER CABING]		CHANGE PLANS		CASING TEST AN		\mathbf{x}	_			
					OTHER					[
OTHER				- - - -	`						
7. Describe Proposed or Co work) SEE RULE 1 103.	ompleted	Operations (Clea	irly state all pertin	ent detail	ls, and give per	tinent dates, i	ncluding e	stimated date	of starting any	proposed	
•	! ha1.	2.00 F	24 10 10 01								
Spudded a 9-1/2'	Tove Tove	e at 3:00 F	'M 1U-12-81.	Ran	23 joints	of 7" 17	7# H-40	ST&C ca	sing		
set at 915'. 1- $\frac{1}{2}$ /350 sacks 50- $\frac{1}{2}$	-rexas	s rattern g	guide shoe a	t 915'	• Flappe	r float a	it 875'	. Cemen	ted		
7/350 sacks 50-1	30 FU2	1 10-14-91	9 . 3% TF-4	& 3% K	CL. Tail	ed in $w/1$.60 sac	ks Class	С		
3% CaCl ₂ . PD 8 held okay. Ceme	obt ci	rculated 3	Bumped pi	ug to	1000 psi,	released	l press	ure & f1	oat		
held okay. Ceme	Nippl	ed un & te	sted to 100	O poi	WUC. Dri	lled out	2:30 P	M 10-15-	81.		
plug & resumed o	lrilli	ing.	sted to 100	J psi,	OK. Red	uced hole	e to 6-	1/4". D	rilled		
		C									
•											
			•	<u> </u>					***		
C. I hereby certify that the	informati	on above is true	and complete to th	e best of i	my knowledge z	and belief.					
11/2. 12 200				P	day on the second of	7 a					
TENED / (Manual !!			<u>/ </u>	r riig	ineering S	secretary		DATE 10	-28-81		
1/	1	`	1								
m	KD.	u/Ma	m_=		OIL AND G	AS INSPE	CTAR		NOV - 3 19	981	