STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

D CJANJVIIIVI DNA 1 DN.	LFAR	LIVIC
40. 07 CBPIET ALCEIVED		
DISTRIBUTION		1
SANTA FE	V	
FILE	V	
U.S.G.S.		
LAND OFFICE		<i>k</i>
OPERATOR	V	

DISTRIBUTION SANTA FE	P O BO	TION DIVISION × 2088 MEXICO 87501 NW 23 '88	Form C-103 · Revised 10-1-78
U.S.G.S.		1801 23 00	Sa. Indicate Type of Leuse State Fee X
LAND OFFICE		O. C. P.	5. State Oli & Gas Lease No.
OPERATOR		ARTESIA, OFFICE	J. Sidle Ch. & Gaz Evaso No.
SUNDRY THIS FORM FOR PROF	NOTICES AND REPORTS ON	WELLS ACK TO A DIFFERENT RESERVOIR. H PROPOSALS.)	
1. GAS GAS WELL WELL	OTHER-		7. Unit Agreement Name
2. Name of Operator	/		8. Farm or Lease Hame
Ralph Nix Oil, Inc.	<u> </u>		Melaine Cattury
3, Address of Operator			9, Well No.
P.O. Box 440, Artes:	La ,NM 88210		1
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER	0 FEET FROM THE East	LINE AND FEET FRO	Atoka Glorieta Yeso
South LINE, SECTION	26 TOWNSHIP 18 S	RANGE 26 E	
	15. Elevation (Show whether 3307 Gr.	DF, RT, GR, etc.)	12. County Eddy
16. Check A	ppropriate Box To Indicate N	lature of Notice, Report or O	ther Data
NOTICE OF IN			IT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUC AND ABANDON	REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT
OTHER Re complete			
17. Describe Proposed or Completed Operators, SEE RULE 1103.	rations (Clearly state all pertinent deta	ails, and give pertinent dates, includin	g estimated date of starting any proposed

Propose to set CIBP @ 2750' Spot 100' cement on top Set 25 SXS plug at 1550' est TOC 1200'

Perforate Grayburg 1094-1128 and stimulate as necessary for production

16. I hereby	certify ther the information shove is true an	d complete to the best of my knowledge and be	oate 11/22/88	
APPROVED BY	Original Sign Mike Will	ned By lams + + + + + + + + + +	NOV 2 8 1988	=