Form 9-331		N" OIL CONS. CON	MISSION	Form Approved.
Dec. 1973	INITED STATES	Drawer DD		Budget Bureau No. 42-R1424
	DEPARTMENT OF THE I	Artesia, NM 882	10 5. LEASE	
			LC 058	
	GEOLOGICAL SURV	/EY	6. IF INDIAN, ALLO	TTEE OR TRIBE NAME
SUNDI	RY NOTICES AND REPO	ORTS ON WELLS	7. UNIT AGREEME	NT NAME
(Do not use th reservoir, Use	his form for proposals to difil or to dee Form 9–331–C for such proposals.)	peREGEIVED to a differen	Ballard Graybur 8. FARM OR LEASE	g San Andres Unit NAME
1. oil K	gas O	OT a a 1000	Tract	7A
		CT 22 1982	9. WELL NO.	
			2	
	darko Production Company SS OF OPERATOR AR		10. FIELD OR WILDO	
		TESIA, OFFICE	Loco Hills-Quee	n-Grayburg-San Andre
4. LOCATIO	O. Box 67, Loco Hills, ON OF WELL (REPORT LOCATION	<u>New Mexico</u> 8825 I CLEARLY. See space 17	AREA	OR BLK. AND SURVEY OR
below.)	FAOR SEAL PHILL COL PR		17 - 1	85 - 29E
	FACE: 560' FNL& 660' FE PROD. INTERVAL: Same AL DEPTH: Same	L Sec. 17,T18S,R2	E 12. COUNTY OR PAR Eddy	NSH 13. STATE New Mexico
· · · · · · · · · · · · · · · · · · ·		<u> </u>	14. API NO.	
REPORT	APPROPRIATE BOX TO INDICAT , OR OTHER DATA	E NATURE OF NOTICE,		
			15. ELEVATIONS (SH	HOW DF, KDB, AND WD)
EQUEST FO	OR APPROVAL TO: SUBSE	QUENT REPORT OF:	3488.3	GL
RACTURE 1 HOOT OR				
EPAIR WEL			<i></i>	
	TER CASING	ŭ	(NOTE: Report results) change on For	of multiple completion or zone
ULTIPLE C		m in the second		
LIANOF TO				
		H		
BANDON*		U U U U U U U U U U U U U U U U U U U		
BANDON* other)	NES	U U U U U U U U U U U U U U U U U U U		
BANDON* other) 7. DESCRIE	NES	PERATIONS (Clearly stal		and give pertinent dates,
BANDON* other) 7. DESCRIE	NES	DPERATIONS (Clearly stat	e all pertinent details,	and give pertinent dates, subsurface locations and
BANDON* other) 7. DESCRIE including measure	NES X Cement sq1 X Cement sq1 BE PROPOSED OR COMPLETED C g estimated date of starting any p ed and true vertical depths for all n	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine	e all pertinent details, lirectionally drilled, give nt to this work.)*	subsurface locations and
BANDON* other) 7. DESCRII including measure otel Ci- ca	NES X Cement squ BE PROPOSED OR COMPLETED (g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was Witnesse	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke.	te all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½"	subsurface locations and production
BANDON* other) 7. DESCRII including measure otel Ci- ca	NES X Cement squ BE PROPOSED OR COMPLETED (g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was Witnesse	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke.	te all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½"	subsurface locations and production
BANDON* other) 7. DESCRIE including measure otel Ci ca: Va Ve:	NES X Cement sqt X Cement sqt Z Cement sqt X Cement sqt X Cement sqt X Cement sqt Composition Statistics State of Starting any p State of Starting and	DPERATIONS (Clearly stat proposed work. If well is o narkers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 2	e all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of	subsurface locations and production
BANDON* other) 7. DESCRIE including measure otel Ci ca: Wa Ve:	NES X Cement squ BE PROPOSED OR COMPLETED O g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was Witnesse terflow between 55" & 8	DPERATIONS (Clearly stat proposed work. If well is o narkers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 2	e all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of	subsurface locations and production
BANDON* other) 7. DESCRIE including measure otel Ci ca: Va Ve: Wo	NES X Cement sqt X Cement sqt X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED O g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was witnesse terflow between 5½" & 8 rbal permission was reed rk @ 9:00 AM 7-14-82:	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 2 ceived from Georg	e all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% o e Stewart to per:	subsurface locations and production il cut. form the following
BANDON* other) 7. DESCRIE including measure otel Ci Ca Ca Va Ve Wo Pla	NES X Cement sqt X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED (g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was witnesse terflow between 5½" & 8 rbal permission was rec rk @ 9:00 AM 7-14-82: an to perforate 2 - 180	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 20 ceived from Georg	te all pertinent details, lirectionally drilled, give int to this work.)* t job on the 5½" 4 BFPD with 5% of a Stewart to per: noles @ 2800' and	subsurface locations and production il cut. form the following d establish
BANDON* other) 7. DESCRIE including measure otel Ci ca: Wa Ve: Wo Pla ci:	NES X Cement sqt X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED (g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was witnesse terflow between 5½" & 8 rbal permission was rec rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and pres	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 2 ceived from Georg 0° phase squeeze is ssure. Set CIBP (te all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to per holes @ 2800' and approximately 2	subsurface locations and production il cut. form the following d establish
BANDON* other) 7. DESCRIE including measure otel Ci Ca: Wa Ve: Wo Pla Ci:	NES X Cement sqt X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED (g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was witnesse terflow between 5½" & 8 rbal permission was rec rk @ 9:00 AM 7-14-82: an to perforate 2 - 180	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 2 ceived from Georg 0° phase squeeze is ssure. Set CIBP (te all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to per holes @ 2800' and approximately 2	subsurface locations and production il cut. form the following d establish
BANDON* other) 7. DESCRIE including measure otel Ci Ca: Wa Ve: Wo Pla Ci:	NES X Cement sqt X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED (g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was witnesse terflow between 5½" & 8 rbal permission was rec rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and pres	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 2 ceived from Georg 0° phase squeeze is ssure. Set CIBP (te all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to per holes @ 2800' and approximately 2	subsurface locations and production il cut. form the following d establish
BANDON* other) 7. DESCRIE including measure otel Ci ca: Wa Ve: Wo Pla ci:	NES X Cement sqt X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED (g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was witnesse terflow between 5½" & 8 rbal permission was rec rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and pres	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 2 ceived from Georg 0° phase squeeze is ssure. Set CIBP (te all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to per holes @ 2800' and approximately 2	subsurface locations and production il cut. form the following d establish
BANDON* other) 7. DESCRIE including measure otel Ci Ca: Wa Ve: Wo Pla Ci:	NES X Cement sqt X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED (g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was witnesse terflow between 5½" & 8 rbal permission was rec rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and pres	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 2 ceived from Georg 0° phase squeeze is ssure. Set CIBP (te all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to per holes @ 2800' and approximately 2	subsurface locations and production il cut. form the following d establish
BANDON* other) 7. DESCRIE including measure otel Ci Ca Va Ve Wo Plu ci cer	NES X Cement squ X Cement squ BE PROPOSED OR COMPLETED (g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was witnesse terflow between 5½" & & rbal permission was rec rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and pres ment to surface or ceme	DPERATIONS (Clearly stat proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 2 ceived from Georg 0° phase squeeze 2 ssure. Set CIBP (ent squeeze water:	e all pertinent details, firectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to per: noles @ 2800' and approximately ; Elow.	subsurface locations and production il cut. form the following d establish 2790' and circulate
BANDON* other) 7. DESCRIF including measure otel Ci Ca Wa Ve: Wo Pla Ci Cer	NES X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED O g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was Witnesse terflow between 5½" & 8 rbal permission was rec rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and pres ment to surface or ceme afety Valve: Manu. and Type	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. B-5/8" casing = 2 ceived from Georg D° phase squeeze is ssure. Set CIBP (ent squeeze water)	e all pertinent details, firectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to per: noles @ 2800' and approximately ; Elow.	subsurface locations and production il cut. form the following d establish 2790' and circulate
BANDON* other) 7. DESCRIF including measure otel Ci Ca Wa Ve: Wo Pla Ci Cer	NES X Cement squ X Cement squ BE PROPOSED OR COMPLETED (g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was witnesse terflow between 5½" & & rbal permission was rec rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and pres ment to surface or ceme	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. B-5/8" casing = 2 ceived from Georg D° phase squeeze is ssure. Set CIBP (ent squeeze water)	e all pertinent details, firectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to per: noles @ 2800' and approximately ; Elow.	subsurface locations and production il cut. form the following d establish 2790' and circulate
BANDON* other) 7. DESCRIF including measure otel Ci Ca: Wa Ve: Wo Pla Ci cer ubsurface S B. I hereby of	NES X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED O g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was Witnesse terflow between 5½" & 8 rbal permission was rec rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and pres ment to surface or ceme afety Valve: Manu. and Type	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. B-5/8" casing = 2 ceived from Georg D° phase squeeze f ssure. Set CIBP (ent squeeze water: d correct	te all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to pert noles @ 2800' and approximately flow.	subsurface locations and production il cut. form the following d establish 2790' and circulate
BANDON* other) 7. DESCRIF including measure otel Ci Ca: Wa Ve: Wo Pla Ci cer ubsurface S B. I hereby of	NES X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED (g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was witnessed terflow between 5½" & & rbal permission was red rbal permission was red rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and press ment to surface or cement afety Valve: Manu. and Type certify that the foregoing is true and MARDANCE	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. B-5/8" casing = 2 ceived from Georg D° phase squeeze 1 ssure. Set CIBP (ent squeeze water: d correct TIPLE Area Super	te all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to pert noles @ 2800' and approximately flow.	subsurface locations and production il cut. form the following d establish 2790' and circulate
BANDON* other) 7. DESCRIF including measure otel Ci Ca: Wa Ve: Wo Pla Ci cer ubsurface S B. I hereby of	NES X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED O g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was witnesse terflow between 5½" & & rbal permission was rec rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and pres ment to surface or ceme afety Valve: Manu. and Type certity that the foregoing is true an APPROVED	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 2 ceived from Georg 0° phase squeeze 1 soure. Set CIBP (ent squeeze water: d correct TITLE Area Super	te all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to pert noles @ 2800' and approximately flow.	subsurface locations and production il cut. form the following d establish 2790' and circulate
measure otel Ci Ca Wa Ve Wo Pla Ci cer ubsurface S 8. Lhereby G	NES X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED O g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was Witnesse terflow between 55" & & rbal permission was red rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and pres ment to surface or ceme afety Valve: Manu. and Type certive that the foregoing is true an certive that the foregoing is true an certive that the foregoing is true an continue to the foregoing is true and to perforate 2 - 180 rculation rate and pres ment to surface or ceme	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 2 ceived from Georg 0° phase squeeze 1 soure. Set CIBP (ent squeeze water: d correct TITLE Area Super	te all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to pert noles @ 2800' and approximately flow.	subsurface locations and production il cut. form the following d establish 2790' and circulate
BANDON* other) 7. DESCRIE including measure otel Ci Ca: Wa Ve: Wo Pla Ci Cer ubsurface S B. Lhereby of GNED	NES X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED O g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was witnesse terflow between 5½" & & rbal permission was rec rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and pres ment to surface or ceme afety Valve: Manu. and Type certity that the foregoing is true an APPROVED	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 2 ceived from Georg 0° phase squeeze 1 soure. Set CIBP (ent squeeze water: d correct TITLE Area Super	re all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to per: noles @ 2800' and approximately flow.	subsurface locations and production il cut. form the following d establish 2790' and circulate
BANDON* other) 7. DESCRIE including measure otel Ci ca: Wa Ve: Wo Pla ci cer ubsurface S 8. Lhereby of GNED	NES X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED O g estimated date of starting any p and true vertical depths for all n rculated 200 sx to pit sing. Job was Witnesse terflow between 5½" & & rbal permission was red rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and pres ment to surface or ceme afety Valve: Manu. and Type certily that the foregoing is true an Correspondent of the foregoing is true and to perforate 2 - 180 rculation rate and pres ment to surface or ceme afety Valve: Manu. and Type (ORIG. SGD.) DAVID R. (APPRO GC F2+0: 1982	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. 8-5/8" casing = 2 ceived from Georg 0° phase squeeze 1 soure. Set CIBP (ent squeeze water: d correct TITLE Area Super	re all pertinent details, lirectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to per: noles @ 2800' and approximately flow.	subsurface locations and production il cut. form the following d establish 2790' and circulate
BANDON* other) 7. DESCRIE including measure otel Ci Ca: Wa Ve: Wo Pla Ci Cer ubsurface S B. Lhereby of GNED	NES X Cement sqt X Cement sqt BE PROPOSED OR COMPLETED O g estimated date of starting any p ed and true vertical depths for all n rculated 200 sx to pit sing. Job was Witnesse terflow between 55" & & rbal permission was red rk @ 9:00 AM 7-14-82: an to perforate 2 - 180 rculation rate and pres ment to surface or ceme afety Valve: Manu. and Type certive that the foregoing is true an certive that the foregoing is true an certive that the foregoing is true an continue to the foregoing is true and to perforate 2 - 180 rculation rate and pres ment to surface or ceme	DPERATIONS (Clearly state proposed work. If well is of markers and zones pertine on primary cemen ed by Arlen Coke. B-5/8" casing = 2 ceived from Georg 0° phase squeeze 1 soure. Set CIBP (ent squeeze water) d correct TILE <u>Area Super</u> space for Federal or State off FILES	e all pertinent details, firectionally drilled, give nt to this work.)* t job on the 5½" 4 BFPD with 5% of e Stewart to per: noles @ 2800' and approximately : Elow. Steviso TATE	subsurface locations and production il cut. form the following d establish 2790' and circulate

:

:

JIS, CEOLOGICUS SUPPRY NOSWELL REVEMEXICO