TITLE OIL ABO BAS ISSPECTOS	AUG 1 0 1982
THE Ralph Nix, Jr	B/5/82
8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
then Stimulate w/gelled water flat.	
Plan to perf Yeso formation $w/50$ shots from 2789' then stimulate $w/gelled$ water frac.	to 3570' &
packed on top of the RBP as a result of frac job	in Yeso Formation.
Intend to set RBP @ 3701.09, there will be more the	
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includit work) SEE RULE 1103.	ing estimated date of starting any proposed
Plug back to Yeso , Perforate & X Stimulate	
OTHER _	
TEMPORARILY ABANDON COMMENTE DRILLING OPHS.  CHANGE PLANS CASING "EST AND CEMENT JOB	PLUG AND APANICHMENT
PERFCRM REMEDIAL WORK PLUG AND ABANDON REMED AL WORK	ALTERING CASING
	NT REPORT OF:
5. Check Appropriate Box To Indicate Nature of Notice, Report or C	TEddy (MAN)
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
THE East LINE SECTION 34 TOWNSHIP 185 PARCE 26E NMP	
UNIT LETTER A . 330 FEET FROM THE NORTH LINE AND 990 FEET FR	
, Location of Well	10. Field and Pool, or *mical
P. O. Box 617 Artesia, New Mexico 88210	1
Ralph Nix	Merrill 9. Well No.
Name of Operator	B, Farm or Lease Name
	7. Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS ARTESIA, OFFICE	
O. C. D.	
LAND OFFICE AUG 6 1982	State Oil & Gas Lesse No.
rice / V	5a. Indicate Type of Lesse
DISTRIBUTION P. O. BOX 2088 RECEIVED	Fart 1-103 - Revised 10-1-78
ENERGY AND MINERALS DEPARTMENT  C _ CONSERVATION DIVISION	•
STATE UP NEW MENCO	