

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Premier Oil & Gas, Inc.

3. Address and Telephone No.

P.O. Box 1246, Artesia, NM 88210;

(505) 748-2093

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit I: 1650' FSL & 990' FEL
Section 22, T-18S R-29E

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

NMLC055696

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Yates Premier Fed. #2

9. API Well No.

30-015-24125

10. Field and Pool, or Exploratory Area

Turkey Track; SR,Q,GB,SA

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Rectification
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Plug
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Premier intends to plug this well in the following manner:

1. Pull rods, pump and tubing.
2. Set CIBP @ 2045' w/35' cement. Pressure test plug to 1000 psi.
3. Circulate hole 2/25# gelled brine.
4. Spot cement plug from 1000' to 900'.
5. Spot cement plug from 400' to 300'.
6. Spot plug @ surface level.
7. Install dry hole marker.
8. Remove equipment & trash; break down location & reseed.

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct

Signed *Les Babyak*

Title President

Date 6/17/98

(This space for Federal or State office use)

(ORIG. SGD.) LES BABYAK

Approved by
Conditions of approval, if any:

Title PETROLEUM ENGINEER

Date JUL 21 1998