GTATE OF NEW ME. ENERGY AND MINERALS DEI				•	
	<del></del>	CONSERVA	TION DIVIS: N		
DISTRIBUTION		P. O. BO	x 2088 RECEIV	eD .	Form C-103
SANTA PE	V	SANTA FE, NEW	MEXICO 87501		Revised 10-1
FILE	77				5a. Indicate Type of Lease
U.S.G.S.			NOV 91	982	State X Fee
LAND OFFICE					
OPERATOR			O. C. D	1	5. State Off & Gas Lease No. 647
IND MOT USE THIS FORM	SUNDRY NOTICE	ES AND REPORTS ON	ACK TO A DIFFERENT MESCAVOIR	1	
OIL X GAS WELL	OTHER.				7, Unit Ayreement Name .
Name of Operator		/			8. Farm or Lease Name.
C.E. LARI	Ì	WELCH			
Address of Operator		9. Well No.			
P. O. BOX 196, ARTESIA, NM 88210					# 1 <del>-B-</del>
					10. Field and Pool, or Wildcat
Location of Well  WHIT LETTER B 330 FEET FROM THE NORTH LINE AND 2270 FEET FROM					ARTESIA Q.B.S.A.
				Ì	
THE LIN	E, SECTION	TOWNSHIP	S MANGE 28E	HMPM.	
m	mmmm.	(Ct. Aleksania	DE PT CD ata 1		12. County
15. Elevation (Show whether DF, RT, GR, etc.) 3573.2' GL					EDDY
	Theck Appropria OF INTENTION		ature of Notice, Repo		er Data REPORT OF:
PERFORM REMICIAL WORK		FLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
EMPORARILY ABANDON			COMMENCE DRILLING OPHS.		PLUG AND ABANDONMENT
PULL OR ALTER CABING		CHANGE PLANS	CASING TEST AND CEMENT JQE	4	
( 01454		. [			
7. Describe Proposed or Comp work) SEE RULE 1103.	oleted Operations (Cl	early state all pertinent deta	ails, and give pertinent dates,	including e	stimated date of starting any propo
11/6/82			4# ST & C casin float set at 40		HOWCO guide
	Cement wit 800# at 6: job sheet	07 PM. HELD.	OWCO "C"+2% cac Circulated 75	l and sacks	bump plug to to pit (HOWCO
	x 460				
	× 1/1 -				

11/7/82

WOC 13 hours. 7:00 AM. Drilled out with 7 7/8" bit. Drilled 30' of cement before shoe. Tested to 1000# 3' below shoe for

m/1. 6/2	The	OIL AND BAS INSPECTED	NOV 1 0 1982
8. I hereby certify that the information of	. /	Accountant	. DATE 11/8/82
	s to drill to TI ent operation is	) 3000' in San A <b>nd</b> res wit s drilling.	n / //8" bit.