

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPI
(Other instructions
verse side)

Form approved
Budget Bureau No. 1004-1000
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC 028978B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR Yates Petroleum Corporation
3. ADDRESS OF OPERATOR 105 South 4th St., Artesia, NM 88210
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

MAY 11 '88

O. C. D.
ARTESIA, OFFICE

660' FNL & 1980' FEL

14. PERMIT NO. API #30-015-25121
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3419' GR

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Benson Deep Fed. ET Com

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Undes. Bone Springs

11. SEC., T., R., M., OR BLM. AND
SURVEY OR ASQA

Unit B, Sec. 33-T18S-R30E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to drill out retainer at 8150' and cement to 8230'.
Clean out to retainer at 8570'.
Perforate 8318-8440' w/25 .42" holes.
Acidize perforations with 3750 gals 15% NEFE acid.
Frac down casing with 100000 gals Versgel 1400 + 180000# 20/40 + 25000# 16/30 sand.
Hang on pump for production test.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Production Supervisor

DATE 5-3-88

(This space for Federal or State office use)

APPROVED BY [Signature]

TITLE

DATE 5-9-88

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

