

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

RECEIVED

Form C-103  
Revised 10-1-78

APR 19 1983

O. C. D.

ARTESIA, OFFICE

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
B-8814

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Yates Drilling Company	8. Farm or Lease Name State KG-30
3. Address of Operator 207 S. 4th, Artesia, N.M. 88210	9. Well No. 2
4. Location of Well UNIT LETTER H 1650' FEET FROM THE North LINE AND 760' FEET FROM THE East LINE, SECTION 30 TOWNSHIP 18S RANGE 28E N.M.P.M.	10. Field and Pool, or Wildcat Artesia f-g-da
15. Elevation (Show whether DF, RT, GR, etc.) 3579.5	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.

Spudded a 12 1/4" hole, 5:00 PM on 4-12-83. PTD 2200'  
Ran 12 joints of 8 5/8" 24# J-55 (495') of casing set 495'. 1-Cement guide shoe set 495'. Insert floast set 445'. Cemented with 300 sacks Class "C" 2% CaCl<sub>2</sub>, 1/4#/sack flocele. PD 9:15 AM 4-13-83. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 15 sacks. WOC. Drilled out 12:00 Midnite 4-13-83. WOC 14 hours and 45 minutes. Cut off and welded on flow nipple. Reduced hole to 7 7/8". Drilled plug and resumed drilling.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul Glavin TITLE Production Clerk DATE 4-18-83

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_