

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

NEW MEXICO OIL CONSERVATION COMMISSION



Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-83

6a. Indicate Type of Lease  
State ☒ Free ☐  
5. State Oil & Gas Lease No.  
647-#350

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Santa Rita Exploration Corp. ✓	8. Farm or Lease Name Illinois
3. Address of Operator P.O. Box 798, Artesia, New Mexico 88210	9. Well No. #1
4. Location of Well UNIT LETTER B, 990 FEET FROM THE North LINE AND 1700 FEET FROM THE East LINE, SECTION 19 TOWNSHIP 18S RANGE 28E N.M.P.M.	10. Field and Pool, or Wildcat Artesia Q GR SA
15. Elevation (Show whether DF, RT, GR, etc.) 3594.8	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Perf & acid job

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug back TD at 2774'

9/27/83 Perforated at 2072, 28, 66, 67, 68, 85, 86, 98, 99, 2100, 01, 27, 28, 29, 33, 34, 35, 81, 82'. Total holes: 19.  
Acidized w/2000 gals. 15% NEFE  
Fraced w/30,000 gal 2% KCL gelled water & 20,000# 20/40 sand & 22,000# 10/20 sand.

9/29/83 Perforated at 1954, 55, 56, 61, 62, 63, 65, 66, 67, 68' Total holes: 10  
Acidized w/ 1000 gals 15% NEFE  
Fraced w/20,000 gals 2% KCL gelled water & 20,000# 20/40 sand and 9,000# 10/20 sand.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Walter J. Judd TITLE Production Clerk DATE Oct. 3, 1983

APPROVED BY Original Signed By Leslie A. Clements TITLE Supervisor District # DATE OCT 4 1983

CONDITIONS OF APPROVAL, IF ANY: