

ckf

RECEIVED BY: Mr. [Signature]
BUREAU OF LAND MANAGEMENT

DRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. **O. C. D.**
ARTESIA, OFFICE ☐ OTHER ☐

2. NAME OF OPERATOR
Fred Pool Operating Co. ✓

3. ADDRESS OF OPERATOR
P.O. Box 1393 Roswell, N.M.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
330' FNL & 2310' FEL
Unit B NW NE

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3509 GR

5. LEASE DESIGNATION AND SERIAL NO.

USA NM 34461
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Arco Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Loco Hills ON GRBG S#

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 21, T-18-S, R-29

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Fred Pool Operating Co submits the following procedure for plugging the captioned well:
TD 3105

1) Set cement plug from TD to 1700' with approximately
175 sacks of Class C cement

2) Set 100' cement plug from 310' to 410' with approximately
25 sacks of Class C cement

3) Set 50' cement surface plug with approximately
10 sacks of Class C cement.

Total of 210 sacks cement. This will be plugged as soon as the permit is approved.

See attachment

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE President

DATE November 29, 19

(This space for Federal or State office use)

APPROVED BY [Signature]

TITLE

DATE 12-12-84

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side