clsF

RECEIVED

Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BURFALLOF LAND MANAGEMENT

JAN 3 0 1992

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES  Do not use this form for proposals to dri  Use "APPLICATION FOR	AND REPORTS ON WELLS  Ill or to deepen or reentry to a different reservoir. R PERMIT—" for such proposals  IN TRIPLICATE  (505) 748–1471  38210  scription)	6. If Indian, Allottee or Tribe Name  7. If Unit or CA, Agreement Designation  8. Well Name and No. Northwestern Shores XR Federal #1  9. API Well No. 30-015-24600  10. Field and Pool, or Exploratory Area.
Unit B, 660' FNL, 1980' FEL, Sec. 27-T18S-R26E  36  12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR		Four Mile Draw-Morrow Gas 11. County or Parish, State  Eddy, NM
TYPE OF SUBMISSION		
Notice of Intent  Subsequent Report  Final Abandonment Notice	Abandonment  Recompletion  Plugging Back  Casing Repair  Altering Casing  Other Clean out, Swab/test	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut-Off  Conversion to Injection  Dispose Water (Note: Report results of multiple completion on Well
Well presently completed in perf RBP aet at 9380' Packer set abo RIH with catch tool and pull RBF perfs 9405-11). RIH and set pa	pertinent details, and give pertinent dates, including estimated date of starting I depths for all markers and zones pertinent to this work.)*  Forations 9405-11', 9330-43', 9324-27 ove perfs. Propose to RU, NUBOP. Unstart 19380'. Clean up hole to 9411', acker above perfs (top perf @ 9314'. 0-90 days. If production is not composed to the composed of the composed o	', 9314-16'. Possible set packer and POOH. (possible sand dumped on Swab and clean up perfs.
14. I hereby certify that the foregoing is traceand correct Signed (Intlant) and Collection (Tax space for Federal or State office use)	Title Production Supervisor	
Approved byConditions of approval, if any:	Title	Date 1/28/92