

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87504

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87504

WELL API NO.
30-015-24607

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
E9261

7. Lease Name or Unit Agreement Name:

Ohio State

8. Well No.
1

9. Pool name or Wildcat
Artesia Q, GR, Sa

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

The Eastland Oil Company

3. Address of Operator

P. O. Box 3488 Midland, Texas 79702

4. Well Location

Unit Letter L 1650 feet from the South line and 990 feet from the West line

Section 16 Township 18-S Range 28-E NMPM County Eddy

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3624 KB

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Casing in Well:

8 5/8" @ 372' - 5 1/2" @ 2874' Cemented to surface-Perfs: @ 2090'-2330'.

(1) Set CIBP @ 2050', load hole w/mud laden fluid & spot 25 sacks cement.

(2) POOH to 650' and pump 70 sack cement to surface.

(3) POOH top off well w/ cement.

(4) Cut off well head and install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Travis Reed

TITLE Agent

DATE 9-24-02

Type or print name Travis Reed

Telephone No. 915-683-6293

(This space for State use)

APPROVED BY Gerry Guye

TITLE

Gerry Guye

Compliance Officer

DATE 10-7-02

Conditions of approval, if any: