

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY
MAY 17 1984
O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
LG 3215

7. Unit Agreement Name

8. Farm or Lease Name
Mesa 20-1 State

9. Well No.
1

10. Field and Pool, or ~~Unit~~ ^{Sub} at
Undes. Artesia 4SA

12. County
Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER

2. Name of Operator
Yates Drilling Company

3. Address of Operator
207 South 4th St., Artesia, NM 88210

4. Location of Well
UNIT LETTER L 2100 FEET FROM THE South LINE AND 330 FEET FROM
THE West LINE, SECTION 20 TOWNSHIP 18S RANGE 28E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3599' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

<input type="checkbox"/> PERFORM REMEDIAL WORK	<input type="checkbox"/> PLUG AND ABANDON	<input type="checkbox"/> REMEDIAL WORK	<input type="checkbox"/> ALTERING CASING
<input type="checkbox"/> TEMPORARILY ABANDON	<input type="checkbox"/> CHANGE PLANS	<input type="checkbox"/> COMMENCE DRILLING OPNS.	<input type="checkbox"/> PLUG AND ABANDONMENT
<input type="checkbox"/> PULL OR ALTER CASING	<input type="checkbox"/> OTHER	<input type="checkbox"/> CASING TEST AND CEMENT JOBS	<input checked="" type="checkbox"/> OTHER <u>Perforate, Treat, Frac</u>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 2510'. WIH and perforated 2407-12' w/10 .48" holes. Acidized zone w/750 gal 15% acid. Swab tested. Set BP above perms 2407-12' and perforated 2262-66' and 2280-82' w/12 .48" holes. Acidized perms 2262-66' and 2280-82' w/750 gal 15% acid. Swabbed to pit. No show of oil. Moved bridge plug to 2193'. Tested to 3500#. WIH and perforated 2132-34' and 2149-52' w/10 .48" holes as follows: 2132-34' (4 holes); 2149-52' (6 holes). Acidized zone (Metex) w/750 gal 15% acid. Swabbed down. Good show of oil. Frac'd w/20000 gal gelled water, 15000# 20/40 sand. Pull packer. Bridge plug set at 2193'. Ran tubing and rods. Install pumping equipment.

Correction on first set of perms: from 2407-14'
to 2407-12'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Supervisor DATE 5-15-84

APPROVED BY [Signature] TITLE Original Signed By
Lodie A. Clements
Supervisor District # DATE MAY 18 1984

CONDITIONS OF APPROVAL, IF ANY: