

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.B.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY
MAY 25 1984
O.C.D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
647

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
Metex Pipe & Supply ☒

3. Address of Operator
POB 1037 Artesia, NM 88210

4. Location of Well
UNIT LETTER 0 510 FEET FROM THE South LINE AND 2269 FEET FROM
THE East LINE, SECTION 16 TOWNSHIP 18S RANGE 28E NMPM.

5. Elevation (Show whether DF, RT, GR, etc.)
3585.5' GL

6. 12. County
Eddy

7. Unit Agreement Name
-

8. Farm or Lease Name
Welch State

9. Well No.
1

10. Field and Pool, or Wildcat
Artesia Qn/Cb/SA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/24/84 TD 2700' Driller Measurement
2697' TD Logger-Ran Comp. Neutron(Turned in with this report)
Ran 2698' of new 20# 5 1/2" LT&C Casing with Howco Shoe(Shoe at 2699'KB)
Insert float set at 2680'
Cement with 400-Sxs Howco Lite + 300-Sxs Howco "C" + .2CFR2 + 5# Salt.
Circulated 50-Sxs to Pits. Bumped Plug to 1000# at 3PM Held-OK 15-Min.
Plans are to complete well and put on the pump. Present operation is waiting on P/U.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wilma Pruitt TITLE Bookkeeper DATE 5/25/84

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE MAY 25 1984

CONDITIONS OF APPROVAL, IF ANY: