

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or to enter to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Premier Production Company

3. Address and Telephone No.

P.O. Box 1246, Artesia, NM 88210 (505) 748-2093

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Section 23: SE/4 SW/4
T-18S R-29E

990' FSL & 1450 FWL

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NMNM17223

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Alice Federal #2

9. API Well No.

30015249700051

10. Field and Pool, or Exploratory Area

Turkey Track, SR, Q, GB, SA

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Amended from 2/10/92
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to pull tubing, pump & rods and plug well in following manner: Place 50 sx cement plug from 2450' back to 1775', tag, plug, load hole with 10# mud; place 25 sx plug at 975' (base of salt is 920'); place 25 sx cement plug at 400' (in and out of surface pipe); place 10 sx cement surface plug. Install marker, fill pits & clean up location.

14. I hereby certify that the foregoing is true and correct

Signed Paul White

Title consulting engineer

Date 11/11/92

(This space for Federal or State office use)

Approved by Orig. Signed by Agent to issue

Title PETROLEUM ENGINEER

Date 12-10-92

Conditions of approval, if any: