## 01-010-2444 10

11-27-84

K

• • • • •

**、** 

CBL 740-2737

CNL

750-2742

**`**.

×

.

• .

. .

.





		NM OIL COMS. Drawer DD Artesia, MM	0044155108 86210	cist
orm 3160-5 RECEIVED UNITED STATES June 1990) DEPARTMENT OF THE INTERIOR 1 8 53 HPUSCEAU OF LAND MANAGEMENT				FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
, Q 53 HIL				5. Lease Designation and Serial No. NMNM17223
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. CARL Use "APPLICATION FOR PERMIT—" for such proposals				6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE				7. If Unit or CA, Agreement Designation
I. Type of Well Q Oil Gas Well Well Other	RECEIVED			8. Well Name and No.
2. Name of Operator Premier Production Company		MAR 1 1 199	4	Alice Federal #2
3. Address and Telephone No.		9.0.0		3001524970 <del>0051</del>
P.O. Box 1246, Artesia, NM 882 4. Location of Well (Footage, Sec., T., R., M., or Survey De		749-04-3		10. Field and Pool, or Exploratory Area Turkey Track (SR,Q,GB,SA)
Section 23: SE/4 SW/4 T-18S R-29E	FSLE	KaSO'FU	W.t.N	11. County or Parish, State Eddy County, NM
12. CHECK APPROPRIATE BOX(		NATURE OF NO	TICE, REPOR	T, OR OTHER DATA
TYPE OF SUBMISSION		TY	PE OF ACTION	
Notice of Intent		bandonment		Change of Plans
Subsequent Report		ecompletion lugging Back		New Construction
Final Abandonment Notice		asing Repair Itering Casing		Water Shut-Off Conversion to Injection
	101	ther Plug & Aba	andon	(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*				
Plugged & abandoned well as per requirements. Ran 2" tubing to 2453'; circulated hole with 10# gelled mud. Spotted 65sx cement plug from 2453' back to 1775' (calculated); trip out with tubing. W.O.C. 2 hours; trip in to tag first plug. Tagged plug at 1800'. Pulled tubing to 975'; filled hole with 10# gelled mud; spotted 25sx cement plug at 975'. Pulled tubing to 400'; spotted 25 sx cement plug. Pulled up and spotted 10 sx plug in and out of casing. Installed and cemented 4" identifying marker. Cleaned up and ripped location; leveled and cut drain slope. Ready for inspection.				
inspection.				Post ID-2
				Post ID-2 3-19-93 PYA
				Approved as to plugging of the well bore. Liability under bond is retained until surface restoration is completed.
14. I hereby certify that the foregoing is true and correct Signed Fame Frankite	TitleCo	onsulting Engi	neer	Date2/25/93
(This space for Federal or State office use) Approved by (ORIG, SGD.) DAVID R. G Conditions of approval, if any:	LASS PE	TROLEUM ENGINEE	R	Date 3-9-93
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.				

Instruction on Reverse Si

A second s

· • • 0.0.0

Composition ( LED TI AAM

•