

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. NM-54184
2. Name of Operator Anadarko Petroleum Corporation	6. If Indian, Allottee or Tribe Name N/A
3. Address and Telephone No. PO Box 37, Loco Hills, NM 88255 505/677-2411	7. If Unit or CA, Agreement Designation N/A
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1650' FNL & 2110' FWL Sec. 11, T18S, R28E	8. Well Name and No. Federal 11 #1
	9. API Well No. 30-015-25086
	10. Field and Pool, or Exploratory Area Empire South, Morrow
	11. County or Parish, State Eddy, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input checked="" type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input checked="" type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRUPU. ND wellhead. NU BOP.
2. Release Baker Lock Set pkr & TOH.
3. RU Wireline Co. Set CIBP at 10,650'. Dump bail 351 sx cement on CIBP. TOH.
4. Set on/off tool, pkr & TCP gun assembly to perforate upper Morrow Zone at 10,596-10,600' & 10,609-10,612'. RDWL.
5. Hydro test tbg to 5000# psi to latch onto on/off tool.
6. Swab tbg dry. ND BOP. NU wellhead. RDPV.
7. Drop bar to perforate Upper Morrow.
8. Test Morrow. WOO.

RECEIVED

JUN 30 1997

14. I hereby certify that the foregoing is true and correct

Signed Howard D. The Kett Title Field Foreman Date 06-23-97

(This space for Federal or State office use)

Approved by (ORIG. SCD) JOE G. LARA Title Petroleum Engineer Date 6/23/97

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side