SUNDRY NOTICES AND REPORTS ON WELLS (BO NOT USE THIS FORM FOR FOLLOW TO DECIDE OF FLUC BACK TO A DIFFERENT RESERVOIR. 7. Unit Agreement Name 011 X Colspan="2">X Colspan="2"X Col	U.S.O.3.	Form C-103 Revised 19-1-78 Sa. Indicate Type of Lease State Fee X S. State Oil & Gas Lease No.
oil X will other. other. 2. Name of Operator 8. Farm or Lease Hame Yates Petroleum Corporation 9. Well No. 3. Address of Operator 9. Well No. 207 South 4th St., Artesia, NM 88210 3 4. Location of Well 10. Field and Pool, or Wildcat whit Letter 1750 rest 1750 rest 22 township 18S RANCE 26E Numput 15. Elevation (Show whether DF, RT, GR, etc.) 3316' GR Eddy	USE "APPLICATION FOR PLANIT -" (FORM C-101) FOR SUCH PROPOSALE.)	7. Unit Agreement Name
3. Address of Operator 207 South 4th St., Artesia, NM 88210 4. Location of Well UNIT LETTER I . 1750 FEET FROM THE South LINE AND 330 FEET FROM THE East LINE, SECTION 22 TOWNSHIP 18S RANCE 26E HMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 12. County Bddy	OIL X CAB WELL OTHER-	Flint GU
4. Location of Well UNIT LETTER I . 1750 FEET FROM THE South LINE AND 330 FEET FROM THE East LINE, SECTION 22 TOWNSHIP 18S RANGE 26E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 12. County Bddy		3
15. Elevation (Show whether DF, RT, GR, etc.) 12. County 1316' GR Eddy	UNIT LETTER I I750 FEET FROM THE South LINE AND 330 FEET FROM	
	15. Elevation (Show whether DF, RT, GR, etc.)	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		er Data REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPHS. PLUG AND ABANDONMENT PULL OR ALTER CABING CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OTHER OTHER COMMENCE OTHER CASING TEST AND CEMENT JQB	TEMPORARILY ABANDON PULL OR ALTER CABING CHANGE PLANS CHANGE PLANS CHANGE PLANS COMMENCE DRILLING OPHS. CHANGE PLANS CHANG	PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 1875'. Ran 45 joints 5-1/2" 14# casing set 1875'. 1-Regular guide shoe set 1875'. Float collar set 1833'. Cemented w/300 sx Class C w/.6% CF-1 and .2% AFS. Compressive strength of cement - 950 psi in 12 hrs. PD 9:00 AM 12-14-84. Bumped plug to 1000 psi, released pressure, held OK. WOC 18 hrs. Tested casing to 1000 psi for 30 minutes, okay. WIH and perforated 1626-1783' w/15 .50" holes as follows: 1626, 35, 41, 45, 58, 67, 75, 86, 91, 97, 1704, 23, 28, 68, and 83'. Acidized perfs 1626-1783' w/2000 gals 15% NEFE acid. WIH and reperforated 1603-1786' w/22 .50" holes as follows: 1603, 10, 16, 38, 43, 48, 52, 63, 69, 72, 79, 82, 88, 96, 1700, 06, 17, 26, 31, 58, 80 and 86'. Frac'd perforations 1603-1786' w/80000 gals gelled KCL water, 10000# 100 Mesh and 180000# 20/40 sand.

18. Whereby certify that the information of	above is true and complet	e to the best of my knowledge and belief.	
	Uitt	mus_Production_Supervisor	DATE <u>1-2-85</u>
APPROVED BY	Original Signed Mike Williams Oll & Gas Inspe	5	JAN 11 1985
CONDITIONS OF APPROVAL, IF ANY:			