

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-25361
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. 06-1409
7. Lease Name or Unit Agreement Name State "CG"
8. Well No. 1
9. Pool name or Wildcat N. Illinois Camp Morrow

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER ☐	
2. Name of Operator Mewbourne Oil Company	
3. Address of Operator P.O. Box 5270 Hobbs, New Mexico 88240 (505) 393-5905	
4. Well Location Unit Letter J : 2310 Feet From The East Line and 1980 Feet From The South Line Section 7 Township 18S Range 28E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3597' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/09/95 MIRU pluggers.
12/08/95 Set CIBP @ 10,150'.
12/09/95 Circulate hole with mud. Spot 25 sks. cement on CIBP @ 10,150'. Spot 25 sks. cement plug @ 7050'. Spot 25 sks. cement plug @ 6200'. Spot 25 sks. cement plug @ 3900'. Spot 25 sks. cement plug @ 2885'.
12/12/95 Tag plug @ 2650'. Pump additional 25 sks. cement plug @ 2650' at States request. Spot 25 sks. cement plug @ 1000'. Spot 25 sks. cement plug @ 400'.
12/13/95 Tag plug @ 510'. Spot 25 sks. cement plug @ 400'. Spot 10 sks. cement surface plug. Set State marker. Cut anchors and clean location.

OIL CONSERVATION DIVISION
SANTA FE, N.M.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert Jones TITLE Engineer DATE 1/02/96
TYPE OR PRINT NAME Robert Jones TELEPHONE NO. _____

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: