

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.O.G.	
LAND OFFICE	
OPERATOR	☒

RECEIVED BY

JAN 15 1986

3a. Indicate Type of Lease	
State ☒	Fee ☐
3. State Oil & Gas Lease No.	
LG-8368	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG SALS TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒	GAS WELL ☐	OTHER ☐
Name of Operator Harvey E. Yates Company		
Address of Operator P. O. Box 1933, Roswell, New Mexico 88201		
Location of Well UNIT LETTER <u>J</u> <u>1980'</u> FEET FROM THE <u>South</u> LINE AND <u>1980'</u> FEET FROM THE <u>East</u> LINE SECTION <u>2</u> TOWNSHIP <u>18S</u> RANGE <u>31E</u> QUAD.		
15. Elevation (Show whether DF, RT, GR, etc.) 3780' GL		
12. County Eddy		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		OTHER <u>New Completion</u> ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/13/85 Perforate 8807-10' & 8710-14' (2 spf)
12/18/85 Acidize w/6000 gal 15% acid & ball sealers-swab test
12/20/85 Set CIBP @ 8695'. Perforate 8492-8596' (1 spf)
12/23/85 Acidize w/3000 gal 7 1/2% Acid.
12/26/85 Frac perfs 8492-8596' w/97,500 gal BS-60 Frac & 258,000# 20/40 sand.
12/28/85 Put well on pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed N. M. Young N. M. Young TITLE Drilling Superintendent DATE 12/31/85
Original Signed By Les A. Clements
Supervisor District 11 DATE JAN 16 1986