

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	☒
LAND OFFICE	☒
OPERATOR	☒

RECEIVED

5a. Indicate Type of Lease
State ☒ ☐
5. State Oil & Gas Lease No.
OG 103

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

JUN 29 '88

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator Fred Pool Drilling, Inc. ✓	8. From or Lease Name Kimberly State
3. Address of Operator P.O. Box 1393, Roswell, N.M. 88201	9. Well No. 1
4. Location of Well UNIT LETTER P 660 FEET FROM THE South LINE AND 330 FEET FROM East TOWNSHIP 18S RANGE 28E	10. Field and Pool, or Wildcat Artesia Queen GR
15. Elevation (Show whether DF, RT, GR, etc.) 3637 Grd	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDON ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any pro work) SEE RULE 1103.

Intention to Plug and Abandon:
July 5, 1988

Set cast iron plug at 1600 ft.
Spot 35 sack cement on top of plug.
Spot 35 sack cement at 500', back to 300'
Spot 10 sack cement plug at top.

Notify N.M.O.C.C. in sufficient time to witness

Plugging

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNER David Pool TITLE Vice President DATE 6-28-88
David Moore TITLE _____ DATE 6/30/88